


PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SMJ 2427 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N S 480.00	✓
2	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N S 1,400.00	X
3	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNITS AND POWER MODULES.	S/N S 800.00	250
4	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIMS. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAYING OF BOTH FRONT DOORS	S/N S 560.00	280
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	S 5,600.00	1500 + 1250 = 2750
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES, LHS FRONT FENDER, RHS FRONT FENDER, RHS FRONT DOOR AND LHS FRONT DOOR.	S 6,000.00	2200
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N S 192.00	✓
TOTAL LABOUR CHARGES		S 15,032.00	


Present
03/03/21

Car-in

3/3/21

wip: 16672

Kiam/Keang



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

E-MAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 2427 H


Adrian

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER Deformed	1 S	2,251.00	✓
2	FRONT BUMPER FIXING PARTS Not new	1 S	407.00	+
3	FRONT BUMPER SECURING STRIP Not new	1 S	71.00	X
4	FRONT BUMPER LOWER GRILLE Not new	1 S	196.00	+
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE Not new	1 S	228.00	X
6	FRONT BUMPER LOWER SPOILER Not new	1 S	535.00	+
7	RADIATOR GRILLE Cracked	1 S	2,326.00	✓
8	RADIATOR GRILLE SENSOR SUPPORT LH / RH ?	2 S	102.00	?
9	RADIATOR GRILLE TOP COVER ?	1 S	189.00	?
10	FRONT BUMPER AIR GUIDE GRILLE LH / RH Not new	2 S	948.00	X
11	FRONT BUMPER CARRIER Not new	1 S	845.00	?
12	FRONT BUMPER FOAM FILLER PIECE Cracked	1 S	124.00	✓
13	FRONT BUMPER TOP COVER Deformed	1 S	127.00	✓
14	FRONT BUMPER GUIDE SECTION LH / RH Not new	2 S	72.00	+
15	FRONT BUMPER REINFORCEMENT BRACKET LH ?	1 S	214.00	?
16	"CAUTION" STICKER ?	1 S	14.00	✓
17	"AIR COND" STICKER ?	1 S	8.00	✓
18	LOCK CARRIER BRACKET ?	1 S	137.00	?
19	LOCK CARRIER BRACKET SUPPORT LH (RH) Not new	2 S	58.00	29
20	FRONT PARKING AID SENSOR Not new	2	TBC	X
SUB TOTAL SPARE PARTS			\$	8,852.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL 6366 2323 FAX 6841 1183
EMAIL: NORA.FHA1@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 2427 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT PARKING AID SENSOR SEAL RING ?	4 S	14.00 ?	
22	HORN LH ?	1 S	126.00 ?	
23	HORN BRACKET LH ?	1 S	29.00 ?	
24	FRONT FENDER LH <i>Scratched</i>	1 S	1,060.00 ✓	
25	FRONT FENDER ATTACHMENT PARTS LH <i>Are new</i>	1 S	53.00 x	
26	FRONT BUMPER CLOSING ELEMENT LH <i>Fender ? & Com ✓</i>	1 S	74.00 ?	
27	FRONT FENDER BRACKET LH <i>? b4 ✓</i>	1 S	35.00 ?	
28	FRONT FENDER BRACE LH <i>? b4 ✓</i>	1 S	118.00 ?	
29	FRONT FENDER CENTER BRACKET LH ?	1 S	49.00 ?	
30	FRONT FENDER REAR BRACKET LH <i>Are new</i>	1 S	35.00 x	
31	FRONT FENDER TRIM LH <i>new</i>	1 S	164.00 ✓	
32	FRONT WHEEL HOUSING LINER LH <i>Are new</i>	1 S	275.00 x	
33	WHEEL HOUSING LINER ATTACHMENT PARTS <i>Are new</i>	1 S	169.00 x	
34	FRONT WHEEL SPOILER LH <i>Are new</i>	1 S	73.00 x	
35	FRONT STONE CHIP GUARD	1 S	51.00 x	
36	FRONT FENDER LEDGE COVER LH - LONG ?	1 S	36.00 ?	
37	FRONT FENDER LEDGE COVER LH - SHORT ?	1 S	16.00 ?	
38	BONNET <i>Dented</i>	1 S	3,312.00 ✓	
39	BONNET ATTACHMENT PARTS <i>Are new</i>	1 S	123.00 x	
40	BONNET HINGE LH / RH <i>Are new</i>	2 S	838.00 x	
SUB TOTAL SPARE PARTS			<u>\$ 6,650.00</u>	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2373 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 2427 H


S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	BONNET IMPACT PROTECTION - CENTER <i>new</i>	1	S	28.00	✓
42	BONNET IMPACT PROTECTION - LH / RH <i>new</i>	2	S	56.00	✓
43	BONNET SOUND ABSORBER <i>new</i>	1	S	343.00	x
44	BONNET STRIKER LH / RH <i>new</i>	2	S	100.00	+
45	BONNET LOCK <i>new</i>	2	S	427.00	+
46	BONNET RELEASE CABLE CENTER <i>new</i>	1	S	58.00	+
47	BONNET RELEASE CABLE COVER <i>new</i>	1	S	10.00	+
48	BONNET RELEASE CABLE CENTER <i>new</i>	1	S	58.00	+
49	RELEASE LEVER <i>new</i>	1	S	14.00	+
50	LED HEADLIGHT LH / RH <i>LH cracked</i>	2	S	15,804.00	7902
51	HEADLIGHT WASHER LIFT CYLINDER LH / RH <i>new</i>	2	S	396.00	?
52	HEADLIGHT WASHER HOSE <i>new</i>	1	S	86.00	x
53	HEADLIGHT LIFT CYLINDER BRACKET LH <i>new</i>	1	S	15.00	x
54	LOCK CARRIER <i>new</i>	1	S	1,016.00	x
55	LOCK CARRIER RADIATOR SUPPORT LH <i>new</i>	1	S	38.00	+
56	RADIATOR COOLANT <i>new</i>	4	S	179.00	x
57	RADIATOR AIR GUIDE LH - LONG <i>new</i>	1	S	32.00	?
58	RADIATOR AIR GUIDE RH - LONG <i>new</i>	1	S	31.00	x
59	RADIATOR AIR GUIDE LH - SHORT <i>new</i>	1	S	16.00	?
60	RADIATOR AIR GUIDE RH - SHORT <i>new</i>	1	S	16.00	x
SUB TOTAL SPARE PARTS		:	\$	18,723.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT

Handwritten signature

Handwritten text: N 016 185 7 x6

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL 6366 2323 FAX 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. 5MJ 2427 H

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	RAIDATOR AIR GUIDE - TOP ? X	1	\$ 16.00	
62	RAIDATOR AIR GUIDE - LOWER ?	1	\$ 22.00	
63	FRONT NO PLATE <i>NBC</i>	S/N	\$ 60.00	
64	SUNDRIES ?		\$ 350.00	
TOTAL SPARE PARTS		:	\$ 34,673.00	
TOTAL LABOUR CHARGES		:	\$ 15,032.00	
GRAND TOTAL		:	\$ 49,705.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Peru
03/03/21