

## CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

ESTIMATE - No . 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info				
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Engine No Make/Model				

Account No	Terms	Date/Time Print	ed	CSE	Ope	rator			WIP No			
LAX00000	Credit	01/03/2021/ 12	2:31	QUE	261	/ Edwin C	aina		27239			
		Description of	Goods /	Services				Qty	Unit Price	Disc%		nount
1000 - 10	RHF DOOR	PNL & RH WING	MIRROR								400	1600.00 1050.00
E PNT98000 RESPRAY	RHF DOOR	& RH WINGMIRRO	₹								430	120.00
	REFIT RH	F DOOR COMPONE	NT T									30.00
	RING ELEC	TRICAL SYSTEM										120.00
		NOSTIC CHECK US	SING HI	-SCAN PRO_	TEST							120.00
USING HI- M SUNDRY		L	= = (<	2상임	17	Ma	અર્	7				40.00
SUPPLY BO M SUNDRY	DY PNL SE	EALANT	50		Ц		21	70				20.00
Sundries M MIRROR AS M PANEL ASS	SY-OUTSIC	DE RR VIEW,RH /		/cuT				1.00 1.00	753.00 1466.00		<u> </u>	753.00 1466.00
MOULDING	ASSY-FRT	DR W/LINE.RH		<ut< td=""><td></td><td></td><td></td><td>1.00</td><td>171.00</td><td></td><td></td><td>171.00</td></ut<>				1.00	171.00			171.00
1 TAPE-FR D	R BLACK F	RAME RR,RH /	, pec					1.00	14.00 48.00			48.00
		NT FRAME,RH / R BELT O/S RH	•	- 40				1.00	54.00			54.00
. <b>.</b>	331-110	. 5227 6/5 1	- '	**II(								
					, (	How Clk	VK	2/3/21	14.791	Λ		
			SURVE	YOR NAME:	_	ten CLK	1	10/2/	4.00%			
			SURVEY	OR SIGNAT	URE:	00-	- Na	AL		-		
1 1000	R. Corker	31 21/	DATE:	1		EX1	11/1 -	7		- 1		
1	, rerofin	,	REMARK	(S:		$\rho / \rho$	, 1	1 si-	- Iu	- 1		
- 5	arvey before : cav dan e ;	e in a series				3 Na	11		J			
Confirm & ac	cepted by	a which in the	i" basi <b>s</b>			•						
# 115		the Aught was the second of th	ard.				7%	GST on	Net <sup>1</sup> 5486.0	-		384.02
1		proportion (normalise to	Lipany	Constitution water				Tota	l Payable	•	5	,870.02
1	edged by Rep			The state of the s								
Authorized s	ignatory	and company stan	ıp						1			

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional party of the second of the recair work has compared for the second of the s estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal on other mention recovered. the rubber seal or other repair requiring the removal of the windscreen.

Page 1 of 1