

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

1/2

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Company
JUNNIMED
SERVICES PTE. LTD.
15 CHANGI NORTH STREET 1
#01-20 I-LOFTS @ CHANGI
Singapore 498765

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

03-03-2021
5211043795
201009404M
30001
2021008240/ 1
26-02-2021
TIOU CHUAN CHEE

License plate	Model code	First registration	VIN	Model	Mileage
SLR9650C	5G13HZ	31-08-2017	WWWZZZAUZHW114519	Golf 1.4 CLBM 92 TSI D7F	96,427

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
5G0807217BNGRU	Cover For Bumper Primed <i>3 scc</i>	1	pcs.	1,247.94	#1	1,247.94	1,335.30
	FRT BUMPER						
5G0919493	Sensor Bracket <i>see</i>	1	pcs.	14.51	#1	14.51	15.53
5G0919493A	Sensor Bracket <i>see</i>	2	pcs.	14.51	#1	29.02	31.05
5G0919494	Sensor Bracket <i>see</i>	1	pcs.	14.51	#1	14.51	15.53
D 180KU2A1	2k-Plastic Adhesive <i>see</i>	1	pcs.	78.91	#1	78.91	84.43
D 822150A1	Bonding Agent For Plastic <i>see</i>	1	pcs.	62.81	#1	62.81	67.21
5G0807050A	Guide Piece	1	pcs.	21.92	#1	21.92	23.45
	RHF SIDE BRACKET <i>2 x scc</i>						
5G0805915 9B9	Retainer For Spoiler Sati <i>2 x scc</i>	1	pcs.	196.53	#1	196.53	210.29
5G0807109AL	Impact Beam	1	pcs.	635.13	#1	635.13	679.59
	REINFORCEMENT <i>2 x scc</i>						
5G0821106A	Fender <i>3 repair</i>	1	pcs.	623.70	#1	623.70	667.36
	RHF						
5G0821136B	Cross Support <i>3 x scc</i>	1	pcs.	33.22	#1	33.22	35.55
	RHF FENDER BRACKET						
N 90817302	Rivetted Cap Nut <i>2 x scc</i>	2	pcs.	2.28	#1	4.56	4.88
5G0601025BTFZZ	Alloy Wheel Aluminium Shi <i>inconsistent</i>	1	pcs.	1,460.49	#1	1,460.49	1,562.72
311601361	Rubber Valve <i>2 x scc</i>	1	pcs.	3.42	#1	3.42	3.66
5G2941006E	Twin Halogen Headlamps <i>scc</i>	1	pcs.	766.69	#1	766.69	820.36
	RHF						
	LABOUR	4	pcs.	840.00	#1 <i>1680</i>	3,360.00	3,595.20
	Spray Painting	4	pcs.	800.00	#1 <i>1600</i>	3,200.00	3,424.00

Quotation valid till 05-03-2021

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	11,753.36	7%	875.94	12,513.36	13,389.30
Total	760.00	11,753.36		875.94	12,513.36	13,389.30

Customer

Service Advisor

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

2/2

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Company
JUNNIMED
SERVICES PTE. LTD.
15 CHANGI NORTH STREET 1
#01-20 I-LOFTS @ CHANGI
Singapore 498765

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

03-03-2021
5211043795
201009404M
30001
2021008240/ 1
26-02-2021
TIOU CHUAN CHEE

License plate	Model code	First registration	VIN	Model	Mileage
SLR9650C	5G13HZ	31-08-2017	WWZZZAUZHW114519	Golf 1.4 CLBM 92 TSI D7F	96,427

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rashu
Hp 90010068
4 days
03/03/21 @ 1000
Resy before paint