

iShare Auto Pte. Ltd.

Co. Reg No: 201939376R

8 Kaki Bukit Avenue 4

#08-09 Premier @ Kaki Bukit

Singapore 415875

Tel: 6341 6789 Fax: 6341 6778

Email: ishareauto@gmail.com



DATE : 08.03.21

TO : AIG MOTOR CLAIMS DEPTS
VEHICLE NO : GBJ7542E
MODEL : TOYOTA DYNA
DATE OF ACCIDENT : 28.02.21
TIME OF ACCIDENT : 12:25HRS

JTFAT 35470K213681
Cecilia

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Drill bit</i>	1	\$ 794.30	\$ 794.30
2	FRONT BUMPER BRACKET RH <i>Best</i>	1	\$ 302.90	\$ 302.90
3	FRONT BUMPER FOGLAMP GARNISH RH <i>M</i>	1	\$ 95.80	\$ 95.80
4	HEAD LAMP (LED) RH <i>lit</i>	1	\$ 980.20	\$ 980.20
5	FRONT STEP PANEL GARNISH RH <i>lit</i>	1	\$ 302.50	\$ 302.50
6	FRONT DOOR RH <i>Drill bit</i>	1	\$ 1,794.20	\$ 1,794.20
7	FRONT DOOR OUTER MOULDING RH <i>new</i>	1	\$ 125.31	\$ 125.31
8	FRONT DOOR OUTER HANDLE RH <i>lit</i>	1	\$ 214.60	\$ 214.60
9	FRONT DOOR HINGE RH <i>new</i>	2	\$ 98.50	\$ 197.00
10	FRONT DOOR WEATHER STRIP RH <i>new lit</i>	1	\$ 205.70	\$ 205.70
11	FRONT DOOR ARCH RUBBER RH <i>lit</i>	1	\$ 102.80	\$ 102.80
12	FRONT DOOR INNER LOCK RH <i>new</i>	1	\$ 316.90	\$ 316.90
13	FRONT DOOR LOCK CATCH RH <i>new</i>	1	\$ 45.80	\$ 45.80
14	FRONT DOOR INNER TRIM BOARD RH <i>ould</i>	1	\$ 697.20	\$ 697.20
15	FRONT DOOR SPEAKER RH <i>new</i>	1	\$ 288.70	\$ 288.70
16	FRONT WHEEL REAR MUDGUARD RH <i>lit</i>	1	\$ 186.70	\$ 186.70
17	FRONT LOWER ARM RH <i>2</i>	1	\$ 867.70	\$ 867.70
18	FRONT KNUCKLE ARM BEARING RH <i>MP</i>	1	\$ 245.60	\$ 245.60
19	FRONT WHEEL HUP RH <i>new</i>	1	\$ 518.20	\$ 518.20
20	FRONT SHOCK ABSORBER RH	1	\$ 396.80	\$ 396.80

TOTAL PRICE \$ 8,678.91
LESS 25% \$ 2,169.73
SUB TOTAL PRICE \$ 6,509.18

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT GRILLE CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
2	FRONT BUMPER FOGLAMP GARNISH CLIP RH (SET) <i>new</i>	1	\$ 40.00	\$ 40.00
3	FRONT STEP PANEL GARNISH CLIP (SET) RH <i>new</i>	1	\$ 50.00	\$ 50.00

TO : AIG MOTOR CLAIMS DEPTS
 VEHICLE NO : GBJ7542E
 MODEL : TOYOTA DYNA
 DATE OF ACCIDENT : 28.02.21
 TIME OF ACCIDENT : 12:25HRS

4	FRONT DOOR PILLAR SEALANT RH <i>new</i>	1	\$ 150.00	\$ 150.00	<i>+</i>
5	FRONT DOOR INNER TRIM BOARD CLIP RH (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	<i>30</i>
6	FRONT DOOR LTA WITH PROTECTOR STICKER <i>new</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
7	FRONT DOOR 'SPICE VILLAGE' STICKER <i>new</i>	1	\$ 550.00	\$ 550.00	<i>200</i>
8	DASHBOARD CLIP (SET) <i>new</i>	1	\$ 150.00	\$ 150.00	<i>+</i>
9	FRONT WHEEL TYRE RH <i>new</i>	1	\$ 350.00	\$ 350.00	<i>+</i>
10	REAR BOX FRONT SIDE PILLAR COVER ALUMINIUM RH <i>new</i>	1	\$ 1,800.00	\$ 1,800.00	<i>+</i>
11	REAR BOX SLIDING DOOR RH <i>Dented</i>	1	\$ 3,800.00	\$ 3,800.00	<i>1400</i>
12	REAR BOX SLIDING STOPPER BRACKET RH <i>Best</i>	1	\$ 120.00	\$ 120.00	<i>80</i>
13	REAR BOX SLIDING DOOR RAILING RH <i>Best Dented</i>	1	\$ 2,400.00	\$ 2,400.00	<i>500</i>
14	REAR BOX SLIDING DOOR LOCK RH <i>Best</i>	1	\$ 150.00	\$ 150.00	<i>80</i>
15	REAR BOX STICKER (SET) <i>new</i>	1	\$ 2,800.00	\$ 2,800.00	<i>800</i>
16	BRAKE OIL	1	\$ 40.00	\$ 40.00	<i>x</i>

3140

TOTAL \$ 12,590.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD ,CUT, ADJUST, KNOCK	\$ 1,600.00	<i>1600</i>
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 1,600.00	<i>1200</i>
3	TO SPRAY TUFF COAT	\$ 250.00	<i>80</i>
4	WIRING, BULB CHECKING	\$ 350.00	<i>30</i>
5	CONDUCT WATER TER LEAKAGE TEST	\$ 80.00	<i>x</i>
6	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 250.00	<i>x</i>
7	TRANFER FRONT DOOR MECHANISM RH	\$ 80.00	<i>✓</i>
8	REFOCUS HEADLAMP BEAM	\$ 60.00	<i>x</i>
9	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	<i>x</i>
10	TO PRESS FRONT WHEEL BEARING	\$ 80.00	<i>x</i>
11	FOUR WHEEL ALIGHMENT	\$ 120.00	<i>x</i>
12	REMOVE AND REFIX RAER BOX SLINDING DOOR	\$ 200.00	<i>150</i>

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **GBJ7542E**
MODEL : **TOYOTA DYNA**
DATE OF ACCIDENT : 28.02.21
TIME OF ACCIDENT : 12:25HRS

13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X
----	--	-----------	---

TOTAL \$ 5,500.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 19,099.18
TOTAL LABOUR COST : \$ 5,500.00
TOTAL REPAIR COST : \$ 24,599.18

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

MICHELLE

SERVICE ADVISOR
MICHELLE
HP : 9856 4815

Adrian L
L/S 08/03/21
09 Days ✓

total: 9446.72
L/S: 7.5K ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: