



# KGC WORKSHOP PTE LTD

Sincere • Secure • Satisfaction

Chia Wan Tong  
14 Ang Mo Kio St 63  
Block B  
Singapore 569116

NOT Notified  
Paying After Paint  
2 days  
11pm 8:00pm

\$2750.00

TP  
Date 18/5/2021  
No of Page : 1/2

Registraion No : SCV 92H  
Accident Date : 24-Dec-20  
Our Ref : TP

Model : Mercedes Benz S400I  
Chassis No: WDD2221652A127508  
Engine Capacity :

S/No	Qty	Items	Unit Price	Amount
1	1	Front Bumper	\$ 1,820.00	\$ 1,820.00 ✓
2	1	Front bumper retainer RHS	\$ 25.20	\$ 25.20 ✓
3	1	Front bumper retainer RHS	\$ 25.20	\$ 25.20 ✓
4	1	Front Bumper towing cover	\$ 60.00	\$ 60.00 ✓
5	1	Front bumper inner bracket 222 880 0103	\$ 345.30	\$ 345.30 ✓
6	1	Front Grille <del>550</del>	\$ 710.00	\$ 710.00 ✓
7	1	Front Grille Chrome Garnish	\$ 485.70	\$ 485.70 ✓
8	1	Front bumper sponge	\$ 220.00	\$ 220.00 ✓
9	1	Front bumper reinforcement	\$ 680.00	\$ 680.00 ✓
10	1	Front Lower Radiator Grille	\$ 155.20	\$ 155.20 ✓
11	1	Headlamp Assy RHS	\$ 5,625.00	\$ 5,625.00 ✓
12	1	Headlamp Assy LHS	\$ 5,625.00	\$ 5,625.00 ✓
13	2	Front center parking sensor x2	\$ 280.00	\$ 560.00 ✓
14	1	Front RADAR Sensor	\$ 1,100.00	\$ 1,100.00 ✓
				\$ 15,776.60
				-10% \$ 1,577.66
Total for spare parts				\$ 14,198.94

## Special Nett

1	1 set	Front Bumper Clips	\$ 50.00	\$ 50.00 ✓
2	1pc	Front Number Plate and bracket	\$ 60.00	\$ 60.00 ✓
Total for SP			\$ 110.00	
Sub-Total for Parts :			\$ 14,308.94	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



**KGC WORKSHOP PTE LTD**  
Sincere • Secure • Satisfaction

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mention repair parts, inclusive of replacement parts.		2501 800.00
2		To putty and spray paint on all accident damage parts and other accident affected areas		2501 700.00
3		To remove and refit reverse sensor & conduct distance safety setting	~	100.00 X
4		To perform ADAS (RADAR SENSOR) calibration	~	300.00 X
5		To check wiring system to facilitate repair and refit the same		120.00 201
6		Apply rust proofing on the adjacent panels	~	100.00 X
TOTAL AMOUNT :				2,120.00
OVERALL COST :				16,428.94