



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 04/02/2021

ESTIMATE

NO : QUOT202102-000065(00)

DATE : 01/03/2021

POLICY NO : 999995580

VEH REG NO : SMP7790T

MAKE/MODEL : MERCEDES BENZ A200
SALOON PROGRESSIVE (R18
LED)

CHASSIS NO : WDD1771872W014205

ENGINE NO : 28291480051523

REG. DATE : 2019

Estimate Repair Cost to Vehicle No : SMP7790T

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Taillamp assy - RH	1	450.00 <i>cm</i>	450.00 <i>✓</i>
2 Taillamp lower bracket - RH	1	85.00 <i>sn</i>	85.00 <i>X</i>
3 Rear bumper	1	880.00 <i>cm</i>	880.00 <i>✓</i>
4 Rear bumper side retainer - RH	1	98.00 <i>diy</i>	98.00 <i>✓</i>
5 Rear bumper sensor	1	138.00 <i>sn</i>	138.00 <i>X</i>
6 Rear bumper sensor seals	6	8.00 <i>nn</i>	48.00 <i>✓</i>
7 Rear bumper clips	15 <i>50sn</i>	5.50 <i>nn</i>	82.50 <i>✓</i>
8 Rear fender - RH	1	1,350.00 <i>R</i>	1,350.00 <i>X</i>
9 Rear fender inner shield clips - RH	20	6.50 <i>nn</i>	130.00 <i>X</i>
			3,261.50
		Add 10%	326.15
			3,587.65
SPECIAL NET			
10 Rear windscreen sealant	1	60.00 <i>nn</i>	60.00 <i>X</i>
			60.00
LABOUR			
11 To remove and refit rear windscreen glass	1	150.00 <i>nn</i>	150.00 <i>X</i>
12 To remove and refit RH rear interior garnishes and trimboard to facilitates the repairs	1	180.00	180.00 <i>801</i>
13 To remove and refit rear bumper sensor	1	100.00	100.00 <i>601</i>
14 To check and rectify wiring system	1	80.00	80.00 <i>201</i>
15 To panel beat and straighten RH rear chassis frame, RH rear fender inner panel, to cut and weld RH rear fender, including replacement of parts and align where necessary, to refit and adjust the same	1	1,200.00	1,200.00 <i>5001</i>
16 To putty and spray paint on affected areas	1	800.00	800.00 <i>4001</i>
			2,510.00
		TOTAL	S\$ 6,157.65
		ADD GST @ 7%	431.04
		GRAND TOTAL	S\$ 6,588.69

SINGAPORE DOLLAR SIX THOUSAND FIVE HUNDRED EIGHTY-EIGHT AND CENTS SIXTY-NINE ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000 FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 04/02/2021

ESTIMATE

NO : QUOT202102-000065(00)

DATE : 01/03/2021

POLICY NO : 999995580

VEH REG NO : SMP7790T

MAKE/MODEL : MERCEDES BENZ A200
SALOON PROGRESSIVE (R18
LED)

CHASSIS NO : WDD1771872W014205

ENGINE NO : 28291480051523

REG. DATE : 2019

Estimate Repair Cost to Vehicle No : SMP7790T

Description	Quantity	Unit Price	Amount
		S\$	S\$

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE