



AP AUTOMOTIVE SERVICES PTE LTD  
 ROC: 202022890H  
 BLOCK 9006  
 TAMPINES STREET 93 #01-202  
 SINGAPORE 528840  
 TEL: 6784 4465  
 FAX: 6787 4886

### Estimation

Date \_\_\_\_\_  
 Vehicle SLJ 9705 X  
 Make/Model MAZDA 6  
 Chassis No. JM6GL1071H0104864

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	BONNET	1		REPAIR
2	BONNET LOCK	1	\$ 217.50	\$ X 217.50
3	BONNET LOCK CATCH	1	\$ 85.90	\$ X 85.90
4	BONNET INSULATOR	1	\$ 419.85	\$ X 419.85
5	BONNET HINGE L+R	2	\$ 83.10	\$ X 166.20
6	BONNET STOPPER	2	\$ 23.50	\$ X 47.00
7	HEADLAMP L+R	2	\$ 3,375.90	\$ LHX <sup>new</sup> RH-af 6,751.80
8	HEADLAMP BRACKET L+R	2	\$ 62.80	\$ LHX <sup>new</sup> RH-dp 125.60
9	FRONT GRILLE ASSY	1	\$ 673.85	\$ X cur 673.85
10	FRONT GRILLE TOP GARNISH	1	\$ 456.20	\$ X un 456.20
11	FRONT GRILLE CHROME L+R	2	\$ 187.30	\$ X un 374.60
12	FRONT GRILLE LOGO - MAZDA	1	\$ 95.00	\$ X un 95.00
13	FRONT BUMPER	1	\$ 1,232.75	\$ de 1,232.75
14	FRONT BUMPER GRILLE	1	\$ 89.65	\$ X un 89.65
15	FRONT BUMPER FOG LAMP RH	1		\$ X -
16	FRONT BUMPER FOG LAMP GARNISH RH	1	\$ 105.00	\$ ? de 105.00
17	FRONT BUMPER FOG LAMP CHROME RH	1	\$ 102.60	\$ de 102.60
18	FRONT BUMPER FOG LAMP INNER BRACKET RH	1		\$ X un -
19	FRONT BUMPER RETAINER RH	1	\$ 31.50	\$ de 31.50
20	FRONT BUMPER REINFORCEMENT BAR	1	\$ 585.90	\$ X un 585.90
21	FRONT BUMPER REINFORCEMENT BAR BRACKET	1		\$ X un -
22	FRONT BUMPER SPONGE	1	\$ 110.65	\$ X un 110.65
23	FRONT FENDER RH	1	\$ 389.20	\$ Rp 389.20
24	FRONT FENDER COWLING RH	1	\$ 161.35	\$ In 161.35
25	FRONT SUPPORT PANEL	1	\$ 511.60	\$ xdg 511.60
26	FRONT SUPPORT PANEL TOP GARNISH	1	\$ 95.80	\$ X un 95.80
27	WIPER WASHER TANK	1	\$ 147.60	\$ de 147.60
28	FRONT HORN L+R	2	\$ 80.50	\$ X un 161.00
29	FRONT ABSORBER RH	1		\$ X -
30	FRONT LOWER ARM RH	1		\$ X -
31	FRONT KNUCKLE RH	1		\$ X -
32	FRONT KNUCKLE BEARING RH	1		\$ X un -
33	FRONT BEARING HUB RH	1		\$ X -
34	FRONT RIM RH	1		\$ X -
				6499.95
				5199.96
			Less 20%	\$ 2,627.62
			<b>Total</b>	\$ <b>10,510.48</b>

S/Nett Items			
1	BONNET INSULATOR CLIPS	1	100 \$ X n n 100.00
2	FRONT NUMBER PLATE	1	120 \$ X n n 120.00
3	FRONT BUMPER CLIPS	1	100 \$ 30 n n 100.00
4	FRONT FENDER COWLING CLIPS	1	100 \$ 10 n n 100.00
5	FRONT SUPPORT PANEL TOP GARNISH CLIPS	1	100 \$ X n n 100.00
6	FRONT TYRE RH	1	800 \$ X n n 800.00
			<b>Total</b> \$ 520.00

460

LABOUR			
1	PANEL BEATING ON AFFECTED AREAS	1	1200 \$ 400 1,200.00
2	SPRAY PAINT ON AFFECTED AREAS	1	1000 \$ 400 1,000.00
3	TO CHECK WIRING AND HEADLAMP FOCUS	1	150 \$ 7 30 150.00
4	TO CHECK WIRING AND FOG LAMP FUNCTION	1	150 \$ 7 30 150.00
5	TO RNR INNER TRIMS AND UPHOLSTERY	1	400 \$ X 7 400.00
6	TO RNR UNDERCARRIAGE	1	250 \$ X 250.00
7	TO RNR WHEEL ALIGNMENT	1	250 \$ X 250.00
8	TO RNR TYRE AND WHEEL BALANCING	1	250 \$ X 250.00
9	TO CHECK WATER LEAK	1	150 \$ X 150.00
10	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	1	600 \$ X 600.00
11	TO PERFORM RUST PROOFING	1	400 \$ 30 400.00
12	TO RNR HORN AND TEST FUNCTION	1	100 \$ X n n 100.00
			<b>Total</b> 860

<b>Parts Replacement Amount</b>	\$	<b>11,030.48</b>
<b>Total Amount For Labour</b>	\$	<b>4,900.00</b>
<b>Total Amount</b>	\$	<b>15,930.48</b>

Tanfah 97495749  
 WP' 3/3/21 @ 5:15pm.  
 c/s Resurvey after repair.  
 4 days  
 Tanfah @ Kuantan.

6097-96  
 c/s \$4900  
 04 days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: