



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV10378/LAI CHEE HEN Reg No/Reg Date SMM4373A / 28/06/201 Date In/Mileage 02/03/2021/ 0 Chassis No KNAF3416MK5047761 Engine No G4FGKH738700 Make/Model KIA/CERATO 1.6 A SR SX G335 Colour/Trim 4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
LAX00000	Credit	01/03/2021/ 14:47	QUK	282 / Kevin Leong	29721				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
E PNT88000	REPLACE FRT LH FENDER, FRT LH DOOR, REAR LH DOOR, REAR LH FENDER, REAR BUMPER & AFFECTED AREA REPAIR ON FRT BUMPER PANEL					6 X 400			2400
E PNT98000	PAINT WORK ON FRT BUMPER, FRT LH FENDER, FRT LH DOOR, REAR LH DOOR, REAR LH FENDER, REAR BUMPER & LH WING MIRROR COVER					6 + 80			2180
E PNT88000	TO TRANSFER FRT & REAR LH DOOR ATTACHMENT TO NEW PANEL								240.00
E PNT88000	TO REMOVE & INSTALL REAR SEAT FOR FACILITATE REPAIR (photo)								120.00
E PNT88000	TO REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR (photo)								120.00
A 13900099	TO REMOVE & INSTALL FUEL TANK FOR FACILITATE REPAIR (photo)								400.00
E PNT88000	REMOVE & INSTALL REAR WINDSCREEN GLASS								240.00
M SUNDRY	TO APPLY WINDSCREEN SEALANT								80.00
M SUNDRY	TO APPLY BODY SEALANT FOR FACILITATE REPAIR								80.00
M SUNDRY	PERFORM RUST PREVENTION								40.00
A 54900099	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								30.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120.00
M SUNDRY	TO TRANSFER FRT LH RIM INCLUDING BALANCING								30.00
A WHEELALIGNMENTBP	To Conduct Computerize Full Wheel Alignment								120.00
E PNT88000									60 120.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



to Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV10378/LAI CHEE HEN Reg No/Reg Date SMM4373A / 28/06/201 Date In/Mileage 02/03/2021/ 0 Chassis No KNAF3416MK5047761 Engine No G4FGKH738700 Make/Model KIA/CERATO 1.6 A SR SX G335 Colour/Trim 4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	01/03/2021/ 14:47	QUK	282 / Kevin Leong	29721			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
TO REMOVE & INSTALL REAR PARKING ASSIST								20 50.00
M SUNDRY								
SUNDRIES								
M	PANEL ASSY-FRONT DOOR,LH	/ 00			1.00	1277.00	20.00	1021.60
M	PANEL ASSY-REAR DOOR,LH	/ 00			1.00	1377.00	20.00	1101.60
M	PANEL ASSY-QUARTER OUTER,LH	/ 00			1.00	1349.00	20.00	1079.20
M	WHEEL ASSY-ALUMINIUM	/ CUT			1.00	926.00	20.00	740.80
M	PANEL-FENDER,LH	/ 00			1.00	430.00	20.00	344.00
M	MOULDING ASSY-FRT DR FRAME,LH	/ nec			1.00	72.00	20.00	57.60
M	W/STRIP ASSY-FR DR BELT O/S LH	/ ? X NM			1.00	80.00	20.00	64.00
M	W/STRIP ASSY-FR DR SIDE LH	/ ? X NM			1.00	102.00	20.00	81.60
M	W/STRIP-FR DR BODY SIDE LH	/ ? X NM			1.00	125.00	20.00	100.00
M	W/STRIP-FR DR BELT I/S LH	/ ? X NM			1.00	43.00	20.00	34.40
M	BASE ASSY-FR DR O/S HANDLE LH	/ ? X NM			1.00	52.00	20.00	41.60
M	MOULDING ASSY-RR DR FRAME,LH	/ nec			1.00	50.00	20.00	40.00
M	W/STRIP ASSY-RR DR BELT O/S LH	/ ? X NM			1.00	75.00	20.00	60.00
M	W/STRIP ASSY-RR DR SIDE LH	/ ? X NM			1.00	102.00	20.00	81.60
M	W/STRIP-RR DR BODY SIDE LH	/ ? X NM			1.00	112.00	20.00	89.60
M	W/STRIP-RR DR BELT I/S LH	/ ? X NM			1.00	39.00	20.00	31.20
M	GUARD-REAR WHEEL,LH	/ X NM			1.00	75.00	20.00	60.00
M	GLASS ASSY-REAR WINDOW	/ ? X NM			1.00	447.00	20.00	357.60
M	SCALP-O/S RR VIEW MIRROR,LH	/ ? X NM			1.00	39.00	20.00	31.20
M	COVER-RR BUMPER	/ BR			1.00	651.00	20.00	520.80
M	COVER-RR BUMPER LWR	/ X NM			1.00	241.00	20.00	192.80
M	COVER-RR BUMPER UNDER,LH	/ X NM			1.00	33.00	20.00	26.40
M	BRACKET ASSY-RR BPR SIDE UPR,L	/ BR			1.00	25.00	20.00	20.00
M	BLACK TAPE-FR DR RR,LH	/ nec			1.00	13.00	20.00	10.40
M	BLACK TAPE-RR DR FR,LH	/ nec			1.00	13.00	20.00	10.40
M	BLACK TAPE-RR DR FRAME RR OTR,	/ nec			1.00	8.00	20.00	6.40

Estimate

Steve (CLKK) 2/3/21, 4.00pm
00-NM PL

Steve (CLKK) 2/3/21, 4.00 pm
00-NM PL

Confirm & accepted by hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Authorized signatory and company stamp

EXPIRE - ?

P/P

Ry B/L SMY

15 day

Nett 14,044.80
7% GST on 14044.80 983.14
Total Payable 15,027.94

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.