

Surveyor : STEVE LKK
 Claim : AIG OD
 DOA : 28.02.2021
 Emailed : 09.04.2021, 12.15pm
 Date Survey : 02.03.2021

VEHICLE NO : SMM 4373 A
 MODEL : KIA CERATO 1.6 A SR SX
 WIP : 29721

Material	:	\$	<u>5,623.20</u>
Labour	:	\$	<u>6,360.00</u>
Sub-Total	:	\$	<u>11,983.20</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>11,683.20</u>
GST 7%	:	\$	<u>817.82</u>
Grand Total	:	\$	<u>12,501.02</u>
Finalise By/Date	:	<u>LOI / 09/04/2021</u>	

☒ REVERT BACK WITHIN 7 DAYS,
 OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
 + 0 Days (0) Public Holiday
 TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 02/03/2021	<table> <tr> <td>Cust No/Name</td><td>/LAI CHEE HEN</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMM4373A / 28/06/2019</td></tr> <tr> <td>Date In/Mileage</td><td>02/03/2021/ 26654</td></tr> <tr> <td>Chassis/Package</td><td>KNAF3416MK5047761 /KC17P(F)</td></tr> <tr> <td>Engine No</td><td>G4FGKH738700</td></tr> <tr> <td>Make/Model</td><td>KIA/CERATO 1.6 A SR SX G335</td></tr> <tr> <td>Colour/Trim</td><td>4SS SILKY SILVER / WK SATURN BLACK</td></tr> </table>	Cust No/Name	/LAI CHEE HEN	Reg No/Reg Date	SMM4373A / 28/06/2019	Date In/Mileage	02/03/2021/ 26654	Chassis/Package	KNAF3416MK5047761 /KC17P(F)	Engine No	G4FGKH738700	Make/Model	KIA/CERATO 1.6 A SR SX G335	Colour/Trim	4SS SILKY SILVER / WK SATURN BLACK
Cust No/Name	/LAI CHEE HEN														
Reg No/Reg Date	SMM4373A / 28/06/2019														
Date In/Mileage	02/03/2021/ 26654														
Chassis/Package	KNAF3416MK5047761 /KC17P(F)														
Engine No	G4FGKH738700														
Make/Model	KIA/CERATO 1.6 A SR SX G335														
Colour/Trim	4SS SILKY SILVER / WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
LAX00000	Credit	08/04/2021/ 15:29	BLK	260 / AiTing	29721				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
E PNT88000	REPLACE DAMAGED PARTS, REPLACE LH FRONT FENDER, LH FRONT DOOR, LH REAR DOOR, LH REAR FENDER, REAR BUMPER, REPAIR FRONT BUMPER, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME							✓	2400.00
E PNT98000	RESPRAY ON FRONT BUMPER, LH FRONT FENDER, LH FRONT DOOR, LH REAR DOOR, LH REAR FENDER, REAR BUMPER, LH WING MIRROR COVER, AND ALL OTHER AFFECTED AREAS TO THE SAME							✓	2180.00
E PNT88000	TRANSFER LH FRONT & LH REAR DOOR ATTACHMENTS TO NEW PANEL							✓	240.00
E PNT88000	REMOVE & INSTALL REAR SEATS TO FACILITATE REPAIR							✓	120.00
E PNT88000	REMOVE & INSTALL REAR BOOT COMPARTMENTS TO FACILITATE REPAIR							✓	120.00
A 13900099	REMOVE & INSTALL FUEL TANK TO FACILITATE REPAIR							✓	400.00
E PNT88000	REMOVE & INSTALL REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST							✓	240.00
M SUNDRY	APPLY REAR WINDSCREEN GLASS SEALANT							✓	80.00
M SUNDRY	APPLY BODY SEALANT ON AFFECTED AREAS							✓	80.00
M SUNDRY	PERFORM RUST PREVENTION ON AFFECTED AREAS							✓	40.00
A 54900099	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							✓	30.00
A 10028901	CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE							✓	120.00
A WHEELALIGNMENTBP	CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT							✓	120.00
E PNT88000	REMOVE & INSTALL REAR PARKING ASSIST TO FACILITATE REPAIR							✓	60.00
M SUNDRY								✓	20.00



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 02/03/2021	<table> <tr> <td>Cust No/Name</td><td>/LAI CHEE HEN</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMM4373A / 28/06/2019</td></tr> <tr> <td>Date In/Mileage</td><td>02/03/2021/ 26654</td></tr> <tr> <td>Chassis/Package</td><td>KNAF3416MK5047761 /KC17P(F)</td></tr> <tr> <td>Engine No</td><td>G4FGKH738700</td></tr> <tr> <td>Make/Model</td><td>KIA/CERATO 1.6 A SR SX G335</td></tr> <tr> <td>Colour/Trim</td><td>4SS SILKY SILVER / WK SATURN BLACK</td></tr> </table>	Cust No/Name	/LAI CHEE HEN	Reg No/Reg Date	SMM4373A / 28/06/2019	Date In/Mileage	02/03/2021/ 26654	Chassis/Package	KNAF3416MK5047761 /KC17P(F)	Engine No	G4FGKH738700	Make/Model	KIA/CERATO 1.6 A SR SX G335	Colour/Trim	4SS SILKY SILVER / WK SATURN BLACK
Cust No/Name	/LAI CHEE HEN														
Reg No/Reg Date	SMM4373A / 28/06/2019														
Date In/Mileage	02/03/2021/ 26654														
Chassis/Package	KNAF3416MK5047761 /KC17P(F)														
Engine No	G4FGKH738700														
Make/Model	KIA/CERATO 1.6 A SR SX G335														
Colour/Trim	4SS SILKY SILVER / WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	08/04/2021/ 15:29	BLK	260 / AiTing	29721

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
SUNDRIES				
S SPECIALISTJOB				✓ 30.00
TRANSFER LH FRONT SPORTS RIM, REPLACE TIRE VALVE, CONDUCT WHEEL BALANCING				
S SPECIALISTJOB				80.00
SUPPLY & REPLACE LH REAR QUARTER GLASS SOLAR FILM - RIKECOOL → Supp.				
X EXC				-300.00
INSURANCE EXCESS				
X PANEL ASSY-FRONT DOOR,LH	1.00	✓ 1277.00	20.00	1021.60
X PANEL ASSY-REAR DOOR,LH	1.00	✓ 1377.00	20.00	1101.60
X PANEL ASSY-QUARTER OUTER,LH	1.00	✓ 1349.00	20.00	1079.20
X WHEEL ASSY-ALUMINIUM	1.00	✓ 926.00	20.00	740.80
X PANEL-FENDER,LH	1.00	✓ 430.00	20.00	344.00
X MOULDING ASSY-FRT DR FRAME,LH	1.00	✓ 72.00	20.00	57.60
X MOULDING ASSY-RR DR FRAME,LH	1.00	✓ 50.00	20.00	40.00
X COVER-RR BUMPER	1.00	✓ 651.00	20.00	520.80
X BRACKET ASSY-RR BPR SIDE UPR,L	1.00	✓ 25.00	20.00	20.00
X BLACK TAPE-FR DR RR,LH	1.00	✓ 13.00	20.00	10.40
X BLACK TAPE-RR DR FR,LH	1.00	✓ 13.00	20.00	10.40
X BLACK TAPE-RR DR FRAME RR OTR,	1.00	✓ 8.00	20.00	6.40
X GLASS & MOULDING ASSY-QUARTER	1.00	252.00	20.00	201.60
X FILM-ANTI CHIPPG LH	1.00	27.00	20.00	21.60
X MIRROR ASSY-OUTSIDE RR VIEW,LH	1.00	559.00	20.00	447.20
Z TEXT				
AIG OD CLAIM				
DOA : 28.02.21				
SURVEYOR STEVE LKK 02.03.21				
REPAIR 15 DAYS				
Guarantee Your Warranty, Maintain with Cycle & Carriage!				

Parts	5,623.20	Nett	11,683.20
Labour	6,030.00	7% GST on	817.82
Standard Menu	0.00		
Specialist Job	110.00	Total Payable	12,501.02
Diagnostics Job	0.00		
Sundry/Others	-80.00		
Total(w/o GST)	11,683.20		

This is not an official tax invoice.
This is a computer generated document, no signature is required.

INSURANCE CO. : AIG

Supplementary Parts For Registration No.: SMM 4373 A

<u>Materials</u>		<u>Cost (\$)</u>	
1	Glass & moulding assy-Quarter	252.00	✓ nec
2	Film-Anti chippg LH	27.00	✓ nec
3	Mirror assy-outside RR view, LH	559.00	✓ cut/BR

Total Materials		838.00	
Less 20% discount		167.60	


Total after discount		670.40	
<u>Labour</u>		<u>Cost (\$)</u>	
1	Supply & replace LH rear quarter glass solar film - Rikecool	80.00	✓

Total labour		80.00	
Total amount		750.40	
7% GST		52.53	

Grand total		\$ 802.93	

Thank You.

Yours faithfully



LOI AI TING
SENIOR OFFICER - ADMIN
KIA SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

CAR NO: SMM 4373A

WIP: 29721

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Glass & mounting (Quarter glass)	? / SUPP		✓ NK	82810 m 6110
2	Film (Fender Sitter Rear LH)	? / SUPP		✓ NK	Done 5/3/21
3	Quarter glass Quarter glass Solar film (Rear LH)	? / SUPP		✓ NK	
4	Rear View Mirror Assy LH	? / SUPP		✓ OR	Done 8/3/21
5		? / SUPP			
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

	DATE	TAKEN BY
PHOTO BEFORE PAINT	10/3/21	SEA
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: Cerato 1.6

SURVEYOR: Steve - Ukk

Work Order: R001385
 License: smm 4373 a
 Technician: 810119 kfsan
 Mileage: 26656
 Date: 22.3.21 16:46

Kia : Cerato/Forte : 2019- (BD/BDm) : without Independent Rear Suspension : Rest of World

Front : Left

Actual	Before	Specified Range
-0°21'	-0°22'	-0°53' 0°07'
4°20'	4°20'	4°00' 5°00'
0°05'	0°05'	-0°03' 0°09'
12°54'*	12°54'*	13°30' 14°30'
12°33'*	12°33'*	12°37' 14°37'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°23'	-0°23'	-0°53' 0°07'
4°50'	4°50'	4°00' 5°00'
0°06'	0°06'	-0°03' 0°09'
12°27'*	12°27'*	13°30' 14°30'
12°04'*	12°04'*	12°37' 14°37'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
0°01'	0°01'	
-0°30'	-0°30'	
0°28'	0°28'	
0°11'	0°11'	-0°06' 0°18'

Rear : Left

Actual	Before	Specified Range
-1°08'	-1°08'	-1°42' -0°42'
0°02'	0°02'	-0°02' 0°16'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-1°23'	-1°24'	-1°42' -0°42'
0°13'	0°13'	-0°02' 0°16'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
0°15'	0°16'	
0°15'	0°15'	-0°04' 0°32'
-0°05'	-0°05'	

* This value is not within specification. Tire wear, handling and safety problems may result.

HOME
 Online
CERATO/FORTE../2019/G 1.6 MPI..
VCI

Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save

ICU
 CLU
 WPC

12/12

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good
EPS	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.	M-E-K-01-00-0241	VCI Ver.	02.51
ECU Ver.	M-E-K-01-00-0182	OS Ver.	Android 10