



Automotive Pte Ltd

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

26/02/2021

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention:- XA017

Page # :- 1

Veh # :- SJG7719J

Veh Model :- TOYOTA ALLION 1.5 A

Estimate# :- CK421582

Claim # :-

ACC. Date :- 26/02/21

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	BOOT LID	1 PC	1,098.20	1,098.20 <i>bt</i>
2.	BOOT LID HINGE RH & LH	1 PC	125.00	125.00 <i>bt</i>
3.	BOOTLID LOGO	1 PC	55.00	55.00 <i>bt</i>
4.	BOOTLID EMBLEM - ALLION	1 PC	45.00	45.00 <i>bt</i>
5.	BOOT LID EMBLEM - A15	1 PC	45.00	45.00 <i>bt</i>
6.	BOOT LID CHROME GARNISH	1 PC	255.00	255.00 <i>bt</i>
7.	BOOTLID WEATHERSTRIP	1 PC	190.00	190.00 <i>bt</i>
8.	BOOTLID LOCK	1 PC	77.50	77.50 <i>bt</i>
9.	TAILLAMP ASSY RH & LH	2 PC	315.00	630.00 <i>bt</i>
10.	REAR END PANEL <i>photo</i>	1 PC	555.00	555.00 <i>bt</i>
11.	REAR END PANEL TOP COVER <i>photo</i>	1 PC	155.00	155.00 <i>bt</i>
12.	REAR BUMPER	1 PC	1,580.00	1,580.00 <i>bt</i>
13.	REAR BUMPER BRACKET RH & LH	2 PC	55.00	110.00 <i>nn</i>
14.	REAR BUMPER RETAINER RH & LH	2 PC	58.00	116.00 <i>bt</i>
15.	REAR BUMPER CLIPS	10 PC	5.00	50.00 <i>bt</i>
16.	REAR BUMPER REFLECTOR LH	1 PC	48.00	48.00 <i>nn</i>
17.	REAR BUMPER SIDE RETAINER RH & LH	2 PC	55.00	110.00 <i>nn</i>
LIST TOTAL S\$				5,244.70
30% DISCOUNT S\$				-1,573.41
<i>Supp</i> Rear keyless Sensor - \$148 <i>nn</i>				\$4005.70
				2803.97
LABOUR :				
TO CUT/WELD REAR END PANEL, KNOCK & STRAIGHTEN REAR BODY MEMBER, SPARE WHEEL PANEL, REMOVE & REPLACE ACCIDENT DAMAGED PARTS, REALIGN ALL CONNECTION				700
				900.00
<i>photo</i> SPRAY PAINT BOOT LID, REAR FENDER RH & LH, REAR END PANEL, SPARE WHEEL PANEL, REAR BUMPER (PEARL COLOUR) <i>photo</i>				1000
				700
REMOVE & REPLACE LUGGAGE COMPARTMENT INNER TRIM, GARNISH, COVERING				1,200.00
				40.
TO APPLY SEAL ON WELDING JOINT				60.00
				30
RUST PROOF AFFECTED AREAS				80.00
				30
LABOUR TOTAL S\$				60.00
				1800
				2,300.00

bizSAFE



Automotive Pte Ltd

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

26/02/2021

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1 140344
Veh # :- SJG7719J
Veh Model :- TOYOTA ALLION 1.5 A
Estimate# :- CK421582
Claim # :-
ACC. Date :- 26/02/21
Terms :- C.O.D Days
Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 5,971.29

GST @ 7 % 417.99

AMOUNT DUE S\$ 6,389.28

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

Tanpin 97415749
"up" 1/3/21 @ 1620
cls Repair after repair
Tanpin 1/3/21 @ 1620
5 days.

2803.99

1800

4603.99

1/3/21 3700

5 days #

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

bizSAFE,