

# JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: AIG ASIA PACIFIC INSURANCE PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING SMT1187D [YOUR INSURED] & SLG9460S [OUR CLIENT]  
ON 25/02/2021.

## ESTIMATED REPAIR COSTS FOR SLG9460S

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	BONNET <i>BT</i>	\$ 1,480.92	✓ 656.20
1PC	BONNET INSULATOR <i>HH</i>	\$ 310.11	X
1PC	BONNET SEAL <i>HH</i>	\$ 150.01	X
1PC	BONNET HINGE LH / RH @ \$98.00 EACH <i>HH</i>	\$ 196.00	X
1PC	HEAD LAMP RH <i>broken</i>	\$ 1,410.28	✓ 878.50
1PC	HEAD LAMP LOWER BRACKET RH <i>HH</i>	\$ 198.14	X
1PC	HEAD LAMP WIRE HARNESS <i>HH</i>	\$ 1,092.00	X
1PC	FRONT BUMPER <i>Dented / torn</i>	\$ 901.72	✓ 451.80
1PC	FRONT BUMPER FOG LAMP GARNISH RH <i>dented</i>	\$ 192.10	✓ 179.50
1PC	FRONT BUMPER UNDER COVER <i>HH</i>	\$ 310.98	X
2PCS	FRONT BUMPER SIDE RETAINER LH / RH @ \$65.00 EACH <i>o/s broken</i>	\$ 130.00	✓ 65.00
1PC	FRONT BUMPER SPONGE <i>torn</i>	\$ 223.49	✓ 161.00
1PC	FRONT REINFORCEMENT BAR <i>Dented</i>	\$ 1,092.10	✓ 345.60
1PC	FRONT SUPPORT PANEL <i>Panel</i>	\$ 1,480.82	✓ 688.10
1PC	FRONT SUPPORT PANEL TOP GARNISH <i>HH</i>	\$ 298.70	X
1PC	A/C CONDENSOR <i>HH</i>	\$ 1,672.40	X
1PC	A/C CONDENSOR DISCHARGE PIPE <i>HH</i>	\$ 782.90	X
1PC	A/C CONDENSOR SUCTION PIPE <i>HH</i>	\$ 674.27	X
1PC	RADIATOR ASSY <i>HH</i>	\$ 1,892.47	X
1PC	RADIATOR FAN MOTOR <i>HH</i>	\$ 492.80	X
1PC	RADIATOR FAN BLADE <i>HH</i>	\$ 299.81	X
1PC	RADIATOR FAN COWLING <i>HH</i>	\$ 401.90	X
1PC	WIPER WASHER TANK <i>dented</i>	\$ 295.20	✓ 182.50
1PC	WIPER WASHER TANK MOTOR <i>HH</i>	\$ 378.01	X
1PC	FRONT FENDER RH <i>Dented</i>	\$ 710.10	✓ 588.00
1PC	FRONT FENDER INNER SHIELD RH <i>torn</i>	\$ 101.00	✓
1PC	FRONT FENDER QUARTER GLASS RH <i>HH</i>	\$ 310.19	X
1PC	FRONT FENDER QUARTER GLASS MOULDING RH <i>HH</i>	\$ 194.92	X
1PC	FRONT WHEEL BEARING RH <i>HH</i>	\$ 210.10	X
1PC	FRONT WHEEL BEARING HUB RH <i>HH</i>	\$ 281.14	X

1PC	FRONT KNUCKLE ARM RH HH	\$ 695.92	X
1PC	FRONT LOWER ARM RH HH	\$ 490.44	X
1PC	FRONT ABSORBER RH HH	\$ 411.71	X
1PC	FRONT STABILIZER LINK RH HH	\$ 159.24	X
1PC	FRONT STABILIZER BAR HH	\$ 319.51	X
1PC	FRONT TIE ROD RH HH	\$ 219.91	X
1PC	FRONT TIE ROD END RH HH	\$ 341.05	X
1PC	STEERING RACK & PINION ASSY HH	\$ 2,390.22	X
1PC	DRIVE SHAFT RH HH	\$ 1,598.17	X
1PC	FRONT BUMPER GRILLE CWT	\$ 328.00	✓ 188.40
1PC	FRONT FENDER RH WHEEL HOUSE PANEL <del>Down</del> rep	\$ 580.00	✓ X

4384.60

3288.45

PARTS SUM: \$ 24,790.75  
 PARTS LESS 25%: \$ 6,197.69  
 PARTS TOTAL: \$ 18,593.06

**LABOUR & SPECIAL NETT ITEMS**

*	TO SUPPLY BONNET INSULATOR CLIPS HH	\$ 50.00	X
*	TO SUPPLY HEAD LAMP CLIPS HH	\$ 50.00	X
*	TO SUPPLY FRONT BUMPER CLIPS HCC	\$ 50.00	20/-
*	TO SUPPLY FRONT BUMPER GRILLE CLIPS HH	\$ 50.00	X
*	TO SUPPLY FRONT BUMPER UNDER COVER CLIPS HH	\$ 50.00	X
*	TO SUPPLY FRONT BUMPER FOG LAMP GARNISH CLIPS HH	\$ 50.00	X
*	TO SUPPLY FRONT BUMPER LOWER LID CLIPS HH	\$ 50.00	X
*	TO SUPPLY FRONT FENDER INNER SHIELD CLIPS HCC	\$ 50.00	15/-
*	TO SUPPLY FRONT FENDER QUARTER GARNISH CLIPS HH	\$ 50.00	X
*	TO SUPPLY 1PC SPORT RIM HH	\$ 800.00	X
*	TO SUPPLY 1PC TYRE HH	\$ 300.00	X
*	TO SUPPLY COOLANT HH	\$ 100.00	X
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 2,400.00	800/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 2,400.00	700/-
*	TO TUFF COAT DAMAGED AREAS	\$ 300.00	40/-
*	TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS	\$ 400.00	HH
*	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	\$ 120.00	HH
*	TO RNR A/C CONDENSOR & REFILL GAS TO FACILITATE REPAIRS	\$ 250.00	HH
*	TO RNR RADIATOR & REFILL COOLANT TO FACILITATE REPAIRS	\$ 250.00	HH
*	TO RNR FRONT FENDER QUARTER GLASS TO FACILITATE REPAIRS	\$ 100.00	HH
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$ 200.00	30/-

35.00

\* TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET \$ 300.00 <sup>44</sup>  
ALL MEMORIES TO FACTORY DEFAULT SETTINGS

1570/-

LABOUR & S/N TOTAL: \$ 8,370.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 26,963.06

02/03/22 @ 1100ms

HTA Author

2/3rd 5 days.

2  
n/a

2kk Auth

4893.45

1/5 3900/-

Repair Limit

Check Part prices.

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: