

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

Auto & General Insurance (Singapore) Pte. Ltd
trading as Budget Direct Insurance
190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore 239924
Tel: 6221 2199

Veron

Quotation

DATE : 02.03.2021
VEH NO : SLC5318T
MODEL : Honda Odyssey
D O A : 27.02.2021
YR REF : SKJ6161X

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLC5318T (HONDA ODYSSEY)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
LIST ITEMS			
1	Rear Number Plate Lamp - LH & RH <i>NE new</i>	2	112.40 X
2	Rear Bumper <i>Distorted</i>	1	768.30 ✓
3	Rear Bumper Side Holder - LH & RH <i>new</i>	2	69.00 ✓
4	Rear Bumper Reflector - LH & RH <i>NE new</i>	2	160.60 X
5	Rear Bumper Side Moulding - LH & RH <i>old</i>	2	310.00 ✓
6	Rear Bumper Side Moulding Garnish - LH & RH <i>Delhd</i>	2	248.20 ✓
7	Reverse Sensor Wire Harness <i>NE new</i>	1	398.40 X
8	Rear End Panel <i>Distorted</i>	1	630.80 ✓
9	Rear End Panel Top Garnish <i>Delhd</i>	1	205.40 ✓
10	Rear End Panel Top Garnish Tool Cover <i>could</i>	1	88.20 ✓
11	Rear End Panel Antenna Sensor <i>could</i>	1	85.10 ✓
12	Rear End Panel Buzzer <i>could</i>	1	75.90 ✓
13	Tail Lamp - LH & RH <i>wt</i>	2	1,642.00 ✓
14	Tail Lamp Panel - LH & RH <i>LH Dented</i>	2	916.40 458.20 ✓
15	Tail Lamp Lower Apron - LH & RH <i>Delhd</i>	2	598.60 ✓
16	Tailgate <i>Distorted</i>	1	1,193.70 ✓
17	Tailgate Lock <i>Joined</i>	1	221.60 ✓
18	Tailgate lock Sticker <i>New</i>	1	28.90 X
19	Tailgate Weatherstripe <i>wt</i>	1	137.40 ✓
20	Tailgate Damper - LH & RH <i>Best</i>	2	506.20 ✓
21	Tailgate Hinges - LH & RH <i>new</i>	2	116.60 X
22	Tailgate Outer Chrome Moulding <i>could</i>	1	284.20 ✓
23	Tailgate Outer Opener Switch <i>new</i>	1	175.50 X
24	Tailgate Side Reflector - LH & RH <i>could</i>	2	763.20 ✓
25	Tailgate Centre Reflector <i>could</i>	1	560.90 ✓
26	Tailgate Inner Trim Board <i>could</i>	1	299.60 ✓
27	Tailgate Wiper Motor <i>Dented</i>	1	297.40 ✓
28	Tailgate Glass Moulding <i>new</i>	1	170.40 ✓
29	Tailgate Pull Pocket <i>Delhd</i>	1	35.10 ✓

RE : ESTIMATE FOR ACCIDENT REPAIR SLC5318T (HONDA ODYSSEY)

30	Honda Logo	<i>new</i>	1	38.90 ✓
31	Rear Fender - LH & RH	<i>LH Buckled</i>	2	2,244.00 1122
32	Rear Fender Inner Shield - LH & RH	<i>LH torn</i>	2	264.20 132.10
33	Rear Fender Inner Trim Board - LH & RH	<i>cracked</i>	2	1,370.80 ✓
34	Rear Fender Outer Garnish - LH & RH	<i>LH cracked</i>	2	652.20 326.10
35	Rear Fender Glass Moulding - LH & RH	<i>LH new</i>	2	150.00 75
36	Rear Fender Wheel House Panel - LH	<i>Reps</i>	1	548.50 X
37	Floor Panel	<i>Distorted</i>	1	1,260.50 ✓
38	Floor Panel Cross Member	<i>new</i>	1	398.50 X
39	Rear Air Con Blower Assy - RH	<i>new</i>	1	1,885.40 X
40	Rear Exhaust Pipe	<i>new</i>	1	709.70 X
41	Rear Exhaust Pipe Mounting		1	35.40 X
42	Rear Exhaust Heat Shield	<i>new</i>	1	96.50 X

13975.80

11180.64

Less 20%

20,754.60

(4,150.92)

16,603.68

S/NET ITEMS

1	Rear Number Plate	<i>Best</i>	1	30.00 ✓
2	Rear Number Plate Holder	<i>Delid</i>	1	30.00 ✓
3	Rear Bumper Clips	<i>new</i>	1 set	30.00 ✓
4	Reverse Sensor	<i>Damaged</i>	1	400.00 300
5	Rear End Panel Top Garnish Clips	<i>new</i>	1 set	20.00 ✓
6	Rear End Panel Sealant	<i>new</i>	1 set	60.00 ✓
7	Tailgate Outer Chrome Moulding clips	<i>new</i>	1 set	20.00 ✓
8	Tailgate Inner Trim Board Clips	<i>new</i>	1 set	30.00 ✓
9	Tailgate Glass Sealant	<i>new</i>	1 set	60.00 ✓
10	Rear Camera	<i>Damaged</i>	1	480.00 380
11	Rear Fender inner Shield Clips	<i>new LH</i>	1 set	40.00 20
12	Rear Fender Inner Trim Board Clips	<i>new</i>	1 set	60.00 ✓
13	Rear Fender Outer Garnish Clips	<i>new</i>	1 set	40.00 20
14	Rear Fender Glass Sealant - LH & RH	<i>new</i>	2	80.00 40
15	Floor Panel Insulator Pad	<i>new</i>	1	280.00 20
16	Floor Panel Sealant	<i>new</i>	1	150.00 80
17	Rear Third Row Seat Assy	<i>not new</i>	1	2,000.00 X

1380

3,810.00

Total Parts

\$ 20,413.68

LABOUR CHARGE

1	To knocking & pull out rear portion & renew parts	\$	2,200.00 1700
2	To putty & spray up paint works	\$	2,000.00 1500

RE : ESTIMATE FOR ACCIDENT REPAIR SLC5318T (HONDA ODYSSEY)

3	To check wiring		\$	100.00	30
4	To remove reverse sensor		\$	100.00	50
5	To remove rear camera		\$	100.00	50
6	To remove upholstery		\$	150.00	120
7	To spray tuff coat		\$	250.00	120
8	To remove tailgate glass		\$	180.00	120
9	To transfer tailgate fittings		\$	150.00	80
10	To remove fuel tank	3850	\$	150.00	80
11	To remove rear exhaust pipe		\$	150.00	X

Total Labour \$ **5,530.00**
Grand Total \$ **25,943.68**

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total 16410.64
2/s: 13.1K

13 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: