

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Tan Kah Leong

Date: 04 Mar 2021

## **Preliminary Advice**

Insured Vehicle No	: GBG4799S		
TP Vehicle No	: SGS41Z	Accident Date	: 26/02/2021
Make	: HONDA FIT	Assignment Date	: 02/03/2021
Date of Inspection	: 02/03/2021	Est. Duration of Repair	: 5
Inspection At	: HWA SENG SPRAY PAINTING CO (160 SIN MING) 160 SIN MING DRIVE, #05-11 SIN MING AUTOCITY SINGAPORE 575722		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,148.32
Revised Amount	:S\$	3,256.56
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,256.56

Lump Sum Repair	:S\$
-----------------	------

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :