

REF: CTZ/ 210001

ASSIGNMENT

Veh No:

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Trailer or

SGS 41Z

Yr Regn:

C.C.

1317

Std / NI / NA

HWA SENG SPRAY PAINTING PTE LTD

160 Sin Ming Drive

#05-11 Sin Ming Autocity

SINGAPORE 575722

(COMPANY REGISTRATION NO.: 202017045G)

TEL: 64533100

62669932

Date of Accident: 26/02/2021

Your Insured

Vehicle No: G BG 4799S

Not Authorized
 Penny B4 pain
 5 days
 83258.56

ESTIMATE REPAIR COSTS TO HONDA FIT REG. NO.: SGS 41 Z

1pc	Tailgate	845.20			\$	
1pc	Tailgate w/strip				917.60	✓
1pc	Emblem 'FIT'				162.90	X
1pc	Tailgate Inner Lock				45.30	✓
1pc	Tailgate Striker				146.30	✓
2pcs	Taillamp	284.30	(\$336.40/pc)	NIS CM	24.70	X
1pc	Rear Bumper	495.			672.80	✓
2pcs	Rear Bumper Retainer		(\$42.10/pc)	NIS DIY	597.80	✓
2pcs	Rear Bumper Reflector		(\$36.50/pc)		84.20	✓
2pcs	Tailgate Absorber		(\$142.90/pc)		73.00	X
					285.80	X

3010.40

Less : 20%

602.08

2408.32

LABOUR & MISC CHARGES

Panel Knocking	800.00	500
Spray Painting	900.00	880
Wire Checking	50.00	20
1 set Reverse Sensor	230.00	200
Ceramic Coating	400.00	200
Labour to Remove & Install Rear windscreen	180.00	120
Inner Seal	100.00	30
Sealant & Clip	80.00	40

TOTAL

5148.32

HWA SENG SPRAY PAINTING PTE LTD

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be reviewed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: