

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 03 May 2021

**Preliminary Advice**

Insured Vehicle No	: YP4809C	Accident Date	: 25/02/2021
TP Vehicle No	: YP6477M	Assignment Date	: 02/03/2021
Make	: ISUZU FTR34P	Est. Duration of Repair	: 3
Date of Inspection	: 23/03/2021		
Inspection At	LIUS BROTHER AUTO WORKSHOP (HQ) LIU'S BROTHER AUTO WORKSHOP, BLK 1 KAKI BT AVE 6 #01-01 AUTO BAY @ KAKI BT SINGAPORE 417883 SINGAPORE 417883		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

RePAIRer's Estimate (Gross)	:S\$	6,480.00
Revised Amount	:S\$	2,550.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,550.00
Lump Sum Repair	:S\$	2,000.00

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :