



S THREE AUTOMOTIVE RECOVERY PTE LTD

NOT Notified
C1 by @ 5800h
Arriving After Paint
5. day

TO :
ATTN : MOTOR CLAIM DEPT.

T/P VEH. NO. : SDG9720L

ESTIMATE REPORT 1st QUOTATION

JOB NO. : _____

OWNER'S PARTICULAR

NAME : YONG MUN KEITH
ADDRESS :
LICENSE NO. : SCN3122C
MAKE / MODEL : BMW 116D
OWNER'S INSURER : NTUC
JOB-CODE : TP S/A :

CONTACT : _____

CHASSIS NO : WBA1V720905C07257

ENGINE NO : _____

ACCIDENT DATE : 27-Feb-21

CLAIM DETAIL

MATERIALS

		QTY	QUO-PRICE	DISC	DISC-PRICE	SUR	REV. PRICE
1	TAILGATE LAMP LH 450	CM	1.00	1494.00	10.00	1344.60	Y ✓
2	TAILGATE LAMP RH	SM	1.00	1494.00	10.00	1344.60	Y X
3	TAILGATE SIDE GARNISH COVER LH	SM	1.00	699.00	10.00	629.10	Y X
4	TAILGATE 1475.40	B	1.00	1980.00	10.00	1782.00	Y ✓
5	TAILGATE TRIMBOARD	SM	1.00	176.00	10.00	158.40	Y X
6	TAILGATE RUBBER BEADING	SM	1.00	389.00	10.00	350.10	Y X
7	TAILLAMP LH 615	CM	1.00	850.00	10.00	765.00	Y ✓
8	TAILLAMP RH	SM	1.00	850.00	10.00	765.00	Y X
9	REVERSE SENSOR ASSY (1SET) C 245.00	Shot	1.00	1644.00	10.00	1479.60	Y 2x
10	REAR BUMPER 1015	Bm	1.00	1870.00	10.00	1683.00	Y ✓
11	REAR BUMPER REFLECTOR LH	SM	1.00	42.00	10.00	37.80	Y X
12	REAR BUMPER REFLECTOR RH	SM	1.00	42.00	10.00	37.80	Y X
13	REAR BUMER INNER FRAME PAD 313	CM	1.00	790.00	10.00	711.00	Y 2
14	REAR BUMPER REINFORCEMENT 615	B	1.00	623.00	10.00	560.70	Y 2
15	REAR BUMPER RETAINER LH 138.50	Dis	1.00	177.00	10.00	159.30	Y ✓
16	REAR BUMPER RETAINER RH	SM	1.00	177.00	10.00	159.30	Y X
17	KEYLESS SENSOR	SM	1.00	285.00	10.00	256.50	Y X
18	REAR BUMPER TOP BEAM LH	R	1.00	155.30	10.00	139.77	Y X
19	REAR BUMPER TOP BEAM RH	R	1.00	155.30	10.00	139.77	Y X
20	REAR END PANEL	B	1.00	1028.00	10.00	925.20	Y 2

21	REAR END PANEL GARNISH	1.00	293.50	10.00	264.15	Y	X
22	REAR EXHAUST PIPE	1.00	1017.00	10.00	915.30	Y	X
23	REAR EXHAUST HEAT SHIELD	1.00	389.20	10.00	350.28	Y	X
24	REAR EXHAUST MOUNTING 2PCS	2.00	120.00	10.00	108.00	Y	X
25	REAR NUMBER PLATE LAMP 2PCS	2.00	76.00	10.00	68.40	Y	X

TOTAL (PARTS) :

16816.30

15134.67

SPECIAL NETT ITEM

1	REAR BUMPER CLIPS 1SET	1.00	50.00	0.00	50.00	Y	✓
2	REAR END PANEL SEALANT	1.00	50.00	0.00	50.00	Y	30.00
3	REVERSE SENSOR WITH HOLDER (1SET)	1.00	1200.00	0.00	1200.00	Y	X
4	REAR NO PLATE	1.00	50.00	0.00	50.00	Y	45.00
5	REAR WINDSCREEN GLASS SEALANT	1.00	50.00	0.00	50.00	Y	40.00
6	REAR WINDSCREEN GLASS INNER SEAL	1.00	50.00	0.00	50.00	Y	30.00
7	REAR WINDSCREEN GLASS PRIMER AND CLEANER	1.00	50.00	0.00	50.00	Y	30.00

TOTAL (PARTS) :

1500.00

1500.00

LABOUR

1	STRAIGHTEN & PANEL BEAT ACCIDENT AREA	1.00	1400.00	0.00	1400.00	Y	700.00
2	SPRAY PAINTING ON ACCIDENT AREA	1.00	1400.00	0.00	1400.00	Y	660.00
3	CHECK & REPAIR WIRING SYSTEM	1.00	120.00	0.00	120.00	Y	20.00
4	RESPRAY KOTE TUFF ON ACCIDENT AREA	1.00	120.00	0.00	120.00	Y	60.00
5	R&R TAILGATE COMPONENTS	1.00	180.00	0.00	180.00	Y	60.00
6	R&R REVERSE SENSOR	1.00	120.00	0.00	120.00	Y	60.00
7	R&R EXHAUST SYSTEM	1.00	200.00	0.00	200.00	Y	X
8	RESET ACCIDENT SYSTEM	1.00	180.00	0.00	180.00	Y	X
9	R&R REAR WINDSCREEN GLASS	1.00	180.00	0.00	180.00	Y	120.00
10	R&R INNER TRIM & CARPET TO REPAIR	1.00	150.00	0.00	150.00	Y	60.00

TOTAL (LABOUR) :

4050.00

4050.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:
Date: