



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel: 6702 4282 Fax: 6702 4202

TP Budget Direct.

Xiao Chen

KDH2015019937

PAGE 1

Vehicle No. GBE8465P TOYOTA HIACE

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (\$)	ADJUSTMENT
PARTS (LIST ITEMS)				
1	REAR BUMPER <i>at</i>		545.10	✓
2	REAR BUMPER SIDE RETAINER LH & RH @\$152.20 <i>new</i>		304.40	+
2	REAR BUMPER STAY LH & RH @\$79.20 <i>new</i>		158.40	+
1	REAR TAILLAMP LH <i>new</i>		285.00	+
1	REAR TAILGATE <i>new</i>		1650.90	+
1	REAR FENDER LH <i>Repr</i>		1445.00	+
1	REAR FENDER INNER TRIM BOARD LH <i>new</i>		859.30	+
1	REAR SLIDING DOOR LH <i>Dented</i>		1712.80	✓
1	REAR SLIDING DOOR LOWER ROLLER LH <i>new</i>		227.50	+
1	REAR KNUCKLE ARM LH		582.30	+
1	REAR KNUCKLE ARM BALL JOINT LH		278.40	+
1	REAR KNUCKLE ARM BEARING LH		310.60	+
1	REAR SHOCK ABSORBER LH		272.45	+
1	REAR STABILIZER BAR LH		781.40	+
1	FRONT DOOR LH <i>Dented</i>		1795.00	1298
1	FRONT DOOR HINGE LH & RH @\$172.20 <i>1 piece Best</i>		344.40	115
1	FRONT DOOR INNER PANEL LH <i>could</i>		600.00	544
1	FRONT BUMPER <i>Distorted</i>		558.90	✓
1	FRONT BUMPER LOWER GRILLE <i>new</i>		195.00	+
2	FRONT BUMPER SIDE RETAINER LH & RH @\$151.00 <i>LH Dgd</i>		302.00	151
1	FRONT BUMPER REINFORCEMENT <i>new</i>		453.00	+
2	FRONT BUMPER CORNER PANEL LH & RH @\$152.00 <i>new</i>		304.00	+
2	FRONT HEADLAMP LH & RH @\$898.20 <i>new LH could</i>		1796.40	2 898.20
1	FRONT KNUCKLE ARM LH <i>Band</i>		582.30	2
1	FRONT KNUCKLE ARM BALL JOINT LH <i>new</i>		278.40	+
1	FRONT KNUCKLE ARM BEARING LH <i>Dgc</i>		310.60	+
1	FRONT SHOCK ABSORBER LH <i>Best</i>		272.45	+
1	FRONT Lower Arm LH <i>bt</i>		781.40	478
<i>F. ext RH step Garnish</i>			17987.40	
<i>Fuse box wire cover \$124.10 could</i>			4496.85	25%
<i>Rear Bumper corner panel \$128.90 Repr +</i>			13490.55	25%
SPECIAL NETT ITEMS				
1 SET	REAR BUMPER CLIPS <i>new</i>		100.00	30
1 SET	FRONT BUMPER CLIPS <i>new</i>		100.00	30
1 SET	FRONT BONNET INSULATOR CLIPS <i>new</i>		100.00	+
1	FRONT DOOR COMPANY STICKER RH <i>new</i>		70.00	30
1	FRONT RIM COVER LH <i>3 at</i>		450.00	80
1	REAR RIM COVER LH		450.00	80
1	FRONT TYRE LH <i>3 new</i>		350.00	+
1	REAR TYRE LH		350.00	+
TOTAL PARTS			15460.55	

8008.25

6006.18

290



ACE AUTOLUTION PTE LTD
 13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
 Singapore 417807
 Tel: 6702 4282 Fax: 6702 4202

PAGE 2

Vehicle No. GBE8465P TOYOTA HIACE

S/N	DESCRIPTION	REPAIRER'S ESTIMATE	ADJUSTMENT
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; replace parts	2000.00	1100 1100
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1800.00	800
3	To remove, refix wiring system at accident damaged areas	210.00	30
4	To conduct water seepage test	120.00	x
5	To perform anti-rust treatment on affected areas	270.00	80
6	To transfer rear boot mechanism	120.00	x.
7	To remove and replace front headlamp beam	120.00	30
8	To apply tuff kote	120.00	80
9	To check diagnostics of vehicle management / control unit, reset memories to specification etc	200.00	x.
10	To remove and replace undercarriage part	250.00	200.
11	To conduct wheel alignment test	150.00	80
Labour Total :		5360.00	
TOTAL (PARTS & LABOUR):		20820.55	

2300

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Adrian Ling.
 L/S 03/03/21
 07 Days.

Total: 8556.18
 L/S: 68K

68K