

320 UBI ROAD 3 SINGAPORE 408649 ACCIDENT REPAIR ESTIMATES

		_		
\cap		\Box	ef	
	11	П	€ı	

Type of Claim : TP	Vehicle No. : YP 7404S
Type of Olaim	Make & Model : ISUZU NPR85UH5AK
	Year of Manufacture : 2016
	Chassis No. :
Ins Company : CHINA TAIPING	Engine No.
Excess :	Policy No. :
Date of Accident : 04.02.2021	Time of Accident :
Suggested Days of Repair :7	In-house Vehicle Assessor
Repair Estimates	Case Owner :
Kepan Estimates	Signature :
Parts (a) Cost / List Price Items \$ 3,680.00	Contact No
Plus/Less 15% \$ 552.00	
Total of Cost / List \$ 3,128.00	TINIE 68485726 JOHARI 68485725
(b) Nett Price Items \$ -	
Less	TP Chin.
Total of Nett Item	
(c) Special Nett Items	Derise.
Total Parts Cost (Appendix A) \$ 3,128.00	
Labour (Appendix B) \$ 900.00	
Total Repair Cost \$ 4,028.00	
The above total will be subjected to 7% G.S.T.	

Name of Surveyor

Company

Survey conducted on

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair:

(c) Resurvey

Required / Not Required

(d) Excess

(e) Signature of surveyor

ACACAC

AC

Spark Car Care
ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649 TEL:68438723/68438736 Fax:67436072

Spare Parts

Vehicle No	: YP 7404S	Case Owner : 0
Make & Model	: ISUZU NPR85UH5AK	Year Manufacture 2016
Chassis No	: JAANPR85HG7100375	<u> </u>
Sales Order	:	Supplier :
Order By	:	Type of Claim : <u>TP</u>

S/No	Part Description	QTY	Cost Price		List Price	Nett Price	S/N	Disposition I Surveyor
1	DOOR HINGES SS SIDE DOOR New	2		\$	320.00	X.		
2	DOOR HANDLE EXTERNAL ASSY WITH	1		\$	960.00	+,		
3	SIDE DOOR WITH GASKET TOIN	1		\$	2,400.00		200	0.
				RC	icing	7 1)	
					1			

Spark Car Care

ComfortDelGro Engineering Pte Ltd 320 UBI ROAD 3 SINGAPORE 408649 Tel: 68438723/68438736 FAX: 67436072

La	b	O	u	r
La	D	O	u	

Vehicle No. :	YP7404S	Case Owner	:		
Make & Mode:	ISUZU NPR85UH5AK	Year of Manufacture	:	2015	

S/No	Labour Description	Esimated Price	Adjusted Price
1	DISMANTLE DAMAGE SIDE DOOR & REPLACE NEW SIDE DOOR ,	\$900.00	400
-	RE-ALIGN , TIGHTEN & SECURE DOOR HINGES	1	700
	INC-MEION, HOHTEN & GEGGNE BOOK FINAGEG		
	AAI MA		
	11 HOU		
	100		
	V V		
		1.700	
		•	
	AZT.	00	
	1) \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	1/2.	
		1	
		h	
	LKK Auto Consultants hence notify the Repairer of the following:		
	 To resurvey before/after spray painting 		
	To display damaged part(s) during resurvey		
	Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis		
	a No illegal modification(s) is allowed		
	Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		
	Acknowledged by Repairer		
	Signature:		
	0.500		

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.