



EUROKARS HABITAT PTE LTD  
27A TANJONG PENJURU, SINGAPORE 609042  
ESTIMATE COST OF REPAIRS



|  |              |                  |                 |           |
|--|--------------|------------------|-----------------|-----------|
| <b>India International Insurance Pte Ltd</b> |              | <b>NAME :</b>    | <b>WIP :</b>    | 42692     |
| 64 Cecil Street                              |              | <b>ADDRESS :</b> | <b>EXCESS :</b> |           |
| IOB Building #04/#05                         |              |                  | <b>DATE:</b>    | 26-Feb-21 |
| Singapore 049711                             |              |                  |                 |           |
| <b>ATTN. :</b>                               | MOTOR CLAIMS | <b>TEL :</b>     |                 |           |
| <b>FAX :</b>                                 |              |                  |                 |           |

|                     |                     |                   |           |                         |                |
|---------------------|---------------------|-------------------|-----------|-------------------------|----------------|
| <b>VEH NO :</b>     | <b>SMR5421L</b>     | <b>DATE IN :</b>  |           | <b>CONTACT PERSON :</b> | JESS 8128 9802 |
| <b>CHASSIS NO :</b> | WMWXU520502L83383   | <b>MILEAGE :</b>  |           | <b>TYPE OF CLAIM :</b>  | THIRD PARTY    |
| <b>MODEL :</b>      | MINI One 5 Door RHD | <b>DATE REG.:</b> | 13-Jan-20 | <b>POLICY NO. :</b>     |                |

**NATURE OF WORKS**

| S/NO | <b>Parts Description</b>  |   |                  |     |      |         |                 |
|------|---------------------------|---|------------------|-----|------|---------|-----------------|
|      | QTY                       |   |                  | 1ST | SUPP | REVISED | PRICES          |
| 1    | REAR BUMPER               | 1 | M51.12.7.380.024 |     |      |         | 999.44          |
| 2    | REAR BUMPER SPOILER       | 1 | M51.12.7.380.030 |     |      |         | 290.29          |
| 3    | PDC HOLDER LH             | 1 | M51.12.7.403.267 |     |      |         | 60.39           |
| 4    | PDC HOLDER RH             | 1 | M51.12.7.403.266 |     |      |         | 60.39           |
| 5    | COVER REAR FOGLIGHT       | 1 | M51.12.7.365.737 |     |      |         | 103.35          |
| 6    | REAR BUMPER REINFORCEMENT | 1 | M51.12.7.300.788 |     |      |         | 571.61          |
| 7    | ULTRASONIC SENSOR         | 2 | B66.20.9.274.428 |     |      |         | 653.12          |
| 8    | SENSOR GASKET             | 4 | B66.20.9.283.203 |     |      |         | 26.80           |
| 9    | RR FOG LIGHT              | 1 | M63.24.6.946.904 |     |      |         | 174.20          |
| 10   |                           | 0 | 0                |     |      |         | -               |
| 11   |                           | 0 | 0                |     |      |         | -               |
|      |                           |   |                  |     |      |         |                 |
|      | <b>TOTAL PARTS</b>        |   |                  |     |      |         | 2,939.59        |
|      |                           |   |                  |     |      |         |                 |
|      | <b>TOTAL PARTS COST</b>   |   |                  |     |      |         | <b>2,939.59</b> |

**SUPPLEMENTARY**

| NO | DESCRIPTION | QTY | PARTS NO | 1st | Supp | REVISED | PRICES |
|----|-------------|-----|----------|-----|------|---------|--------|
| 1  |             |     |          |     |      |         |        |
| 2  |             |     |          |     |      |         |        |
| 3  |             |     |          |     |      |         |        |
|    |             |     |          |     |      |         |        |

**Labour Description**

|   |  |  |  |  |  |      |          |
|---|--|--|--|--|--|------|----------|
|   |  |  |  |  |  |      |          |
| 1 | TO REPLACE REAR BUMPER, BUMPER SPOILER . TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. |  |  |  |  |      | 1,260.00 |
|   |  |  |  |  |  |      |          |
| 2 | TO RESPRAY REAR BUMPER .   |  |  |  |  |      | 1,000.00 |
|   |  |  |  |  |  |      |          |
| 3 | TO TRANSFER THE REVERSE SENSORS.   |  |  |  |  |      | 250.00   |
|   |  |  |  |  |  |      |          |
| 4 | TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.                                     |  |  |  |  | NETT | 250.00   |
|   |  |  |  |  |  |      |          |

|   |   |                    |  |      |                 |
|---|---|--------------------|--|------|-----------------|
| 5 | TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS. |                    |  | NETT | 350.00          |
|   |   |                    |  |      |                 |
| 6 | SUNDRIES.                                       |                    |  | NETT | 50.00           |
|   |   |                    |  |      |                 |
|   |   |                    |  |      |                 |
|   |   | TOTAL LABOUR       |  | -    | <b>3,160.00</b> |
|   |   | TOTAL PARTS        |  | -    | <b>2,939.59</b> |
|   |   | TOTAL              |  | -    | <b>6,099.59</b> |
|   |   | LESS EXCESS        |  | -    | -               |
|   |   | TOTAL AFTER EXCESS |  | -    |                 |
|   |   | GST 7%             |  | -    | -               |
|   |   | <b>GRAND TOTAL</b> |  | -    | -               |

**REMARKS:**

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED