

REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.

SUNDRIES.

NETT 250 350.00

NETT 20 50.00

TOTAL LABOUR

2210 - 3,100.00

TOTAL PARTS

- 2,939.59

TOTAL

- 6,099.59

LESS EXCESS

-

TOTAL AFTER EXCESS

-

GST 7%

-

GRAND TOTAL

-

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED

Paul
Hp 90010068

3 days

04/03/21 @ 1050

Resuy before print

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



EUROKARS HABITAT PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS

EUROKARS GROUP

India International Insurance Pte Ltd
64 Cecil Street
IOB Building #04/#05
Singapore 049711

NAME :
ADDRESS :
TEL :

WIP : 42692
EXCESS :
DATE: 26-Feb-21

ATTN. :
FAX :
MOTOR CLAIMS

VEH NO : SMR5421L
CHASSIS NO : WMWXU520502L83383
MODEL : MINI One 5 Door RHD
DATE IN :
MILEAGE :
DATE REG.: 13-Jan-20
CONTACT PERSON : JESS 8128 9802
TYPE OF CLAIM : THIRD PARTY
POLICY NO. :

NATURE OF WORKS							
Parts Description							
S/NO	QTY	1ST SUPP	REVISED	PRICES			
1	REAR BUMPER <i>de /</i>	1	M51.12.7.380.024	999.44			
2	REAR BUMPER SPOILER <i>See /</i>	1	M51.12.7.380.030	290.29			
3	PDC HOLDER LH <i>See /</i>	1	M51.12.7.403.267	60.39			
4	PDC HOLDER RH <i>See /</i>	1	M51.12.7.403.266	60.39			
5	COVER REAR FOGLIGHT <i>? xsv</i>	1	M51.12.7.365.737	103.35			
6	REAR BUMPER REINFORCEMENT <i>? xsv</i>	1	M51.12.7.300.788	571.61			
7	ULTRASONIC SENSOR <i>x sv</i>	2	B66.20.9.274.428	653.12			
8	SENSOR GASKET <i>see /</i>	4	B66.20.9.283.203	26.80			
9	RR FOG LIGHT <i>? xsv</i>	1	M63.24.6.946.904	174.20			
10		0	0	-			
11		0	0	-			
TOTAL PARTS				2,939.59			
TOTAL PARTS COST				1437.31			2,939.59

SUPPLEMENTARY

NO	DESCRIPTION	QTY	PARTS NO	1st Supp	REVISED	PRICES
1						
2						
3						
Labour Description						
1	TO REPLACE REAR BUMPER, BUMPER SPOILER . TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.				840	1,260.00
2	TO RESPRAY REAR BUMPER .				800	1,000.00
3	TO TRANSFER THE REVERSE SENSORS.				150	250.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.				NETT 150	280.00