



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SJV626K

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No	48651
Reg No/Reg Date	SJV626K / 06/02/2018
Date In/Mileage	/ 0
Chassis No	WDD2050402R362057
Engine No	27491031239937
Make/Model	MB/MB C 180 SEDAN (W205) "AVANTGARDE / A
Colour/Trim	021 149 Polar White/ 041 115 SilkBeige/B

Account No	Terms	Date/Time Printed	CSE	Operator			
WC000668	Credit	01/03/2021/ 15:50	AQ	305 / Alan Quek Ai Lun			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount

M BPNSUN
POLICY NO/ACC DATE : 11045893 // 25-02-2021
DRIVE IN: 01-03-2021 // TP CAR NO: GBD6944S (CHINA TAIPING INSURANCE)
DATE IN/DATE SURVEY:
BY/AUTHORIZED ON :

A BPILAB
USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO
STANDARD SETTINGS.NETT

A BPILAB
REMOVE & REPLACE FRONT BUMPER & REMOVE FRONT SUPPORT
ASSY COMPONENTS & REFINISH.

A BPIRES
RESPRAY FRONT BUMPER

M FRT BUMPER

M RH/F BASIC MOUNTING FOR BUMPER

M FRT TOP BASIC MOUNTING FOR BUMPER

M CT/F IMPACT ABSORBER

0.10 380.00

1440.00

720.00

1.00 1620.84 00.00 1620.84

1.00 85.01 00.00 85.01

1.00 90.91 00.00 90.91

1.00 167.75 00.00 167.75

ESTIMATE

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cvclecarriage.com.sg

Confirmed & accepted by

	Nett	4,504.51
7% GST on	4504.51	315.32

Total Payable	4,819.83
----------------------	-----------------

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany