



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-6500111-X

ESTIMATE FOR SJV626K

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information
WIP No 48651
Reg No/Reg Date SJV626K / 06/02/2018
Date In/Mileage / 0
Chassis No WDD2050402R362057
Engine No 27491031239937
Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A
Colour/Trim 021 149 Polar White/ 041 115 SilkBeige/B

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
WC000668	Credit	01/03/2021/ 15:50	AQ	305 / Alan Quek Ai Lun				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : 11045893 / 25-02-2021 DRIVE IN: 01-03-2021 / TP CAR NO: GBD6944S (CHINA TAIPING INSURANCE) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :							0.10	380.00
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT								960 1440.00
A BPILAB REMOVE & REPLACE FRONT BUMPER & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH.								600 720.00
A BPIRES RESPRAY FRONT BUMPER					1.00	1620.84	00.00	1620.84
M FRT BUMPER cut					1.00	85.01	00.00	85.01
M RH/F BASIC MOUNTING FOR BUMPER ? xsn					1.00	90.91	00.00	90.91
M FRT TOP BASIC MOUNTING FOR BUMPER ? xsn					1.00	167.75	00.00	167.75
M CT/F IMPACT ABSORBER ? xsn								

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cvcyclecarriage.com.sg

Rose
Hp 9186 5112
3 days
30/03/21 P1510
Resy before print

Confirmed & accepted by

7% GST on Net 4,504.51
4504.51 315.32

Total Payable 4,819.83

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany