

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EQI21002804/T1VD3E2

Date: 30/03/2021

REFERENCE

Handling Insurer: EQ Insurance Company Ltd Policy No: DMPPHQ21-000903
Claimant Vehicle No : SHA4679R Insured Vehicle No : SLV9218Y
Date of Loss: 27/02/2021 Nature of Claim: TP Claim No: DM21HO00330

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHA4679R**
Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A) Engine No: 2ZRS043162
Reg. Date: 25/05/2017 (Man. Year: 2017) Chassis No: JTDKB3FU903556949
Colour: Blue Odometer: 600510 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm
Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,234.80	2,731.85	502.95	15.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,560.00	1,085.00	475.00	30.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,794.80	3,816.85	977.95	20.40
Approved Total (Overridden) (S\$)		3,100.00		
(S\$)	4,794.80	3,100.00	1,694.80	35.35
+ GST 7.00/7.00% (S\$)	335.64	217.00	118.64	35.35
Nett Amount (S\$)	5,130.44	3,317.00	1,813.44	35.35

INSPECTION

Date of Assignment: 02/03/2021 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected: 02/03/2021 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969
Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Mar 2021)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA4679R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	458.60 FL	*458.60 FL
2	1		*REAR BUMPER REINFORCEMENT	Bent	318.80 FL	*318.80 FL
3	1		*REAR BUMPER CENTER GUARD	Deformed	552.60 FL	*552.60 FL
4	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
5	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	112.70 FL	*- FL
6	1		*REAR BUMPER EXTENSION LH	Torn	232.00 FL	*232.00 FL
7	1		*TAILLAMP UPPER LH	Not Necessary	557.90 FL	*- FL
8	1		*TAILLAMP LOWER LH	Cut	548.40 FL	*548.40 FL
9	1		*TAILGATE OUTER GARNISH	Cracked	889.70 FL	*889.70 FL
10	1		*TAILGATE EMBLEM-PRIUS	Necessary	60.80 FL	*60.80 FL
11	1		*TAILGATE EMBLEM-HYBRID	Necessary	52.40 FL	*52.40 FL
12	1		*TAILGATE EMBLEM-TOYOTA STAR	Necessary	52.90 FL	*52.90 FL
13	1		*TAILGATE COMFORTDELGRO	Necessary	30.00 F	*30.00 F
14	1		*TAILGATE 65521111	Necessary	30.00 F	*30.00 F
15	1		*TAILGATE APPS STICKER	Necessary	40.00 F	*40.00 F
16	1		*REVERSE SENSOR	Distorted	135.70 F	*135.70 F
17	1		*REAR BUMPER MAT	Necessary	50.00 F	*50.00 F
18	1		*REAR NO.PLATE WITH TRIM COVER	Dented	55.00 F	*55.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	4,199.50	3,528.90
- List Item Discount on L Items 25.00/25.00% (S\$)	964.70	797.05
Total Parts (S\$)	3,234.80	2,731.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	525.00
2	SPRAY PAINTING	New	600.00	500.00
3	CHECK LIGHTINGS/ WIRINGS	New	40.00	30.00
4	R/I REVERSE SENSOR	New	120.00	30.00
Gross Labour Cost (\$\$)			1,560.00	1,085.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >