

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT (SUPPLEMENTARY #1)

Our File No: CS/EQI21002804/T1VD3E2

Date: 30/03/2021

REFERENCE

Handling Insurer: EQ Insurance Company Ltd Policy No: DMPPHQ21-000903
Claimant Vehicle No : SHA4679R Insured Vehicle No : SLV9218Y
Date of Loss: 27/02/2021 Nature of Claim: TP Claim No: DM21HO00330

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHA4679R
Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A) Engine No: 2ZRS043162
Reg. Date: 25/05/2017 (Man. Year: 2017) Chassis No: JTDKB3FU903556949
Colour: Blue Odometer: 600510 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	60.00	60.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	60.00	60.00	0.00	0.00
+ GST 7.00/7.00% (S\$)	4.20	4.20	0.00	0.00
Nett Amount (S\$)	64.20	64.20	0.00	0.00
+ Previous Recommendations (S\$)		0.00		
Nett Liability (S\$)		64.20		

INSPECTION

Date of Assignment: 04/03/2021 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected: 02/03/2021 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969
Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Mar 2021)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA4679R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEE	New	60.00	60.00
Gross Labour Cost (\$\$)			60.00	60.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >