

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21002808/T1BA3Q2
Date: 02/08/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MPC0004883
Claimant Vehicle No :	GBJ7468L	Insured Vehicle No :	SJC5634D
Date of Loss:	20/02/2021	Nature of Claim:	TP
		Claim No:	MPC2021D0000784

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ7468L		
Make & Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Engine No:	1KD2861020
Reg. Date:	08/08/2019 (Man. Year: 2019)	Chassis No:	JTFAT35Y60K213798
Colour:	Black	Odometer:	39851 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/75 R15	Rear Tyre Size:	155 R12 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,597.70	2,691.30	3,906.40	59.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,822.40	2,562.40	2,260.00	46.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,420.10	5,253.70	6,166.40	54.00
+ GST 7.00/7.00% (S\$)	799.41	367.76	431.65	54.00

Nett Amount (S\$)	12,219.51	5,621.46	6,598.05	54.00
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,028.91		

INSPECTION

Date of Assignment: 02/03/2021

Date Inspected: 22/03/2021

Estimated Period of Repair: 4.0 days

Inspected At: Borneo Motors (S) Pte Ltd (Pandan)
2 Pandan Crescent
Singapore 128462

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 21 Jul 2021)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ7468L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	30.00 FS	*30.00 FS
2	1		*FRT NUMBER PLATE	Bent	68.00 FS	*68.00 FS
3	1		*FRT RH DOOR COMPANY LOGO -STICKER	Not Necessary	1,440.00 FS	*- FS
4	1		*BUMPER SUB-ASSY FR	Deformed	748.90 FS	*748.90 FS
5	1		*ARM SUB-ASSY ,FR	Not Necessary	262.20 FS	*- FS
6	1		*ARM SUB-ASSY ,FR	Not Necessary	262.20 FS	*- FS
7	1		*BRACKET ,FR BUMPER	Not Necessary	48.40 FS	*- FS
8	1		*COVER ,FOG LAMP ,RH	Not Necessary	62.80 FS	*- FS
9	1		*GRILLE ,RADIATOR	Cut	595.20 FS	*595.20 FS
10	1		*ORNAMENT ,RADIATOR	Necessary	70.50 FS	*70.50 FS
11	6		*RETAINER ,DOOR TRIM	Not Necessary	36.60 FS	*- FS
12	1		*HEADLAMP ASSY ,RH	Cut	1,178.70 FS	*1,178.70 FS
13	1		*R/FRONT DOOR PANEL	Repair	1,794.20 FS	*- FS
					Total Parts (S\$)	6,597.70
						2,691.30

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK LIGHTING & WIRING SYSTEM	New	122.40	122.40
2	TO RESET ECU AND REPROGRAMME	New	180.00	180.00
3	REPLACE FRT RH ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN FRT RH ACCIDENT AFFECTED AREAS	New	2,160.00	1,080.00
4	RESPRAY JOB ON FRT RH ACCIDENT AFFECTED AREAS	New	2,360.00	1,180.00
Gross Labour Cost (\$\$)			4,822.40	2,562.40

Report was unsubmitted during this print-out.

< END OF ESTIMATES >