

# BIFROST AUTO PTE LTD

## REPAIR ESTIMATE

DATE: 2-Mar-21

INSURANCE: MSIG

MODEL: TOYOTA PRIUS

VEHICLE NO.: SHD6529L

DESCRIPTION	QTY	LIST PRICE	AMOUNT	
REAR BUMPER <i>Cut</i>	1	\$642.04	\$642.04	✓
REAR BUMPER SIDE RETAINER <i>SN</i>	1	\$157.78	\$157.78	X
REAR BUMPER CLIPS <i>Hec</i>	1	\$30.80	\$30.80	✓
REAR BUMPER SIDE CLIP <i>HH</i>	1	\$35.00	\$35.00	X
TAIL LAMP ASSY (UPPER) G5 <i>HH</i>	1	\$942.90	\$942.90	X
TAIL LAMP ASSY (LOWER) G5 <i>HH</i>	1	\$860.58	\$860.58	X
REAR FENDER, LH <i>Demol</i>	1	\$1,171.38	\$1,171.38	✓ 836.70
REAR FENDER SIDE PANEL (LH) <i>HH</i>	1	\$231.00	\$231.00	X
REAR FENDER SHIELD (LH) <i>HH</i>	1	\$187.88	\$187.88	X
REAR DOOR RUBBR SEAL OUTER <i>HF</i>	1	\$361.06	\$361.06	X
PANEL SUB-ASSY, REAR DOOR, LH <i>Demol</i>	1	\$1,761.62	\$1,761.62	✓ 1294.90
REAR DOOR HINGE UPPER <i>HH</i>	1	\$115.22	\$115.22	✓
REAR DOOR HINGE LOWER <i>HH</i>	1	\$115.22	\$115.22	✓
REAR DOOR CHECK <i>HH</i>	1	\$214.20	\$214.20	X
REAR DOOR TRIMBOARD <i>HH</i>	1	\$1,015.00	\$1,015.00	X
MOTOR, POWER WINDOW REGULATOR FRT, LH <i>HH</i>	1	\$1,318.52	\$1,318.52	X
REGULATOR, FRONT DOOR WINDOW REAR, LH <i>HH</i>	1	\$319.76	\$319.76	X
DOOR CENTRE PILLAR <i>Demol</i>	1	\$2,226.84	\$2,226.84	✓ 1590.60
PANEL SUB-ASSY, FRONT DOOR, LH <i>Demol / Bru</i>	1	\$1,769.60	\$1,769.60	✓ 1300.97
FRONT DOOR OUTER HANDLE (LH) <i>HH</i>	1	\$530.46	\$530.46	X
FRONT DOOR INNER LOCK <i>HH</i>	1	\$964.32	\$964.32	X
FRONT DOOR HINGE UPPER <i>HH HH HH</i>	1	\$115.22	\$115.22	X
FRONT DOOR HINGE LOWER <i>HH HH HH</i>	1	\$127.68	\$127.68	X
FRONT DOOR CHECK <i>HH</i>	1	\$214.93	\$214.93	X
FRONT DOOR TRIMBOARD <i>HH</i>	1	\$1,015.00	\$1,015.00	X
FRONT DOOR OUTER MOULDING <i>SVL</i>	1	\$264.04	\$264.04	X
FRONT DOOR HANDLE BASE <i>HH</i>	1	\$402.78	\$402.78	X
FRONT DOOR WHETHER STRIP <i>HH</i>	1	\$641.06	\$641.06	X
FRONT DOOR RUBBER SEAL <i>HH</i>	1	\$359.80	\$359.80	X
MOTOR ASSY, POWER WINDOW FRT, LH <i>HH</i>	1	\$1,318.52	\$1,318.52	X
REGULATOR, FRONT DOOR WINDOW FRT, LH <i>HH</i>	1	\$319.76	\$319.76	X
MIRROR ASSY, OUTER REAR VIEW, LH <i>broken</i>	1	\$2,420.18	\$2,420.18	✓ 1374.20
KEY LOCK ANTENNA <i>HH</i>	1	\$436.80	\$436.80	X
FRONT DOOR COMFORT LOGO <i>Hec</i> <i>SN</i>	1	\$105.00	\$105.00	✓ SN
CENTRE ROCKER PANEL (GARNISH) <i>distorted / Demol</i>	1	\$806.40	\$806.40	✓ 576.00
REAR TYRE (LH) <i>SVL</i>	1	\$302.40	\$302.40	X
REAR TYRE RIM (LH) <i>distorted / Bru</i>	1	\$2,177.00	\$2,177.00	✓ 1570.55
REAR WHEEL HUB CAP (LH) <i>distorted / HH</i>	1	\$248.78	\$248.78	✓ 177.10
REAR WHEEL BEARING ING & HUB <i>Down</i>	1	\$854.28	\$854.28	✓ 493.00
REAR CROSS MEMBER <i>HH</i>	1	\$3,080.56	\$3,080.56	X
REAR SHOCK ABSORBER <i>distorted</i>	1	\$165.62	\$165.62	✓
REAR SHOCK ABSORBER MOUNTING <i>HH</i>	1	\$175.42	\$175.42	X
REAR LOWER ARM <i>distorted</i>	1	\$696.50	\$696.50	✓ 497.50

REAR UPPER ARM <i>2 distors</i>	1	\$499.52	\$499.52
REAR KNUCKLE ARM <i>2 distors</i>	1	\$1,134.84	\$1,134.84
REAR COIL SPRING <i>44</i>	1	\$267.96	\$267.96
REAR COIL SPRING MOUNTING <i>44</i>	1	\$0.00	\$0.00
REAR BRAKE ABS SENSOR (WIRE) <i>44</i>	1	\$110.32	\$110.32
REAR STABILIZER BAR <i>44</i>	1	\$436.10	\$436.10
REAR STABILIZER LINK <i>44</i>	1	\$212.24	\$212.24
REAR TRAILING ARM <i>2 distors</i>	1	\$439.88	\$439.88
REAR ASSIST ARM <i>2 distors</i>	1	\$479.08	\$479.08
FRONT FENDER HYBRID EMBLEM, LH <i>44</i>	1	\$121.10	\$121.10
<b>SUB TOTAL</b>			<b>\$34,919.95</b>
<b>LESS 20% 25%</b>			<b>\$6,983.99</b>
<b>DISCOUNTED TOTAL</b>			<b>\$27,935.96</b>
REAR BUMPER RUBBER MAT <i>44</i>	SN	1	\$70.00
REAR DOOR COMFORT & APPS STICKER <i>44</i>	SN	1	\$112.00
<b>SUB TOTAL</b>			<b>\$182.00</b>
<b>Labour Charge</b>			
Panel Beating	1	\$1,800.00	\$1,800.00
Spray Painting Charge	1	\$1,800.00	\$1,800.00
Wiring Charge	1	\$120.00	\$120.00
Tuff Kote	1	\$150.00	\$150.00
Towing Charge	1	\$80.00	\$80.00
Remove/Refix Cushion & Upholstery Rear	1	\$150.00	\$150.00
Remove/Refix Rear Windscreen Glass		\$120.00	\$0.00
Remove/Refix Reverse Sensor	1	\$120.00	\$120.00
Remove/Refix Undercarriage (RR)	1	\$400.00	\$400.00
Re-set Rear ABS System	1	\$400.00	\$400.00
Remove/Refix Fuel Tank	1	\$80.00	\$80.00
Remove/Refix Exhaust Pipe	1	\$80.00	\$80.00
Transfer of Door Mechanism FRONT	1	\$80.00	\$80.00
Re-set Frt Power Window System	1	\$200.00	\$200.00
Transfer of Door Mechanism REAR	1	\$80.00	\$80.00
Re-set Rear Power Window System	1	\$200.00	\$200.00
Four Wheel Alignment	1	\$120.00	\$120.00
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00
<b>TOTAL LABOUR</b>			<b>\$6,410.00</b>
<b>ESTIMATE TOTAL</b>			<b>\$34,527.96</b>

✓ 356.80  
 ✓ 810.60  
 X  
 X  
 X  
 X  
 X  
 ✓ 314.20  
 ✓ 342.20  
 X

12604.22  
 9453.16

✓  
 ✓  
 287.00

1200/-  
 1000/-  
 30/-  
 40/-  
 44  
 80/-  
 44  
 40/-  
 150/-  
 44  
 44  
 60/-  
 44  
 60/-  
 44  
 60/-  
 180/-

2900.00

prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

03/03/2021 @ 1100hrs 7/1P 12,640.16

HA Andrew F  
 Part by RA - 7 days

nja  
 LKK Auto

That after repair  
 with damaged part

**LKK Auto Consultants** hence notify the Repairer of the following:
 

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

 Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_