



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CHAN KIAN CHUAN			Ref: CC4/ASM21002814/Ags3q2 Date: 05/01/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SH 7430D	Veh. Inspected	GBK 8033X
	Policy No.	P2419138	Coverage (\$)	0.00
	Claim No.	S1M032AA	Excess (\$)	0.00
	Assign From		Assign Date	02/03/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	JTFAT35Y20K215953	Colour	WHITE
	Odometer	94195 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/75 R15	BRIDGESTONE	6 mm
	L/H Front Tyre	195/75 R15	BRIDGESTONE	6 mm
	R/H Rear Tyre	155 R12	BRIDGESTONE	6 mm
	L/H Rear Tyre	155 R12	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	05/02/2021	Inspection Date	09/03/2021
	Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	