

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21002819/EGS3Q2
Date: 05/07/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MPC0004809
Claimant Vehicle No :	SLU7473U	Insured Vehicle No :	SJW2811Z
Date of Loss:	28/02/2021	Nature of Claim:	TP
		Claim No:	MPC2021D0000924

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU7473U		
Make & Model:	CITROEN C4 PICASSO, 1.6 BLUEHDI EAT6 (A)	Engine No:	10JBHD3087244
Reg. Date:	13/12/2017 (Man. Year: 2017)	Chassis No:	VF73ABHZTHJ772777
Colour:	Silver	Odometer:	73292 km
Engine Capacity:	1560 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 4 mm	Rear Left Side:	Yokohama 4 mm
Front Right Side:	Yokohama 4 mm	Rear Right Side:	Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,958.00	2,830.00	2,128.00	42.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,560.00	2,410.00	2,150.00	47.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,518.00	5,240.00	4,278.00	44.95
+ GST 7.00/7.00% (S\$)	666.26	366.80	299.46	44.95

Nett Amount (S\$)	10,184.26	5,606.80	4,577.46	44.95
+ Car Rental (6.0 x S\$100.00/day + 7.00% GST) (S\$)		642.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,250.80		

INSPECTION

Date of Assignment: 02/03/2021

Date Inspected: 23/03/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
 209 Pandan Gardens
 Singapore 609339

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 May 2021)
Parts:	143	CITROEN C4 PICASSO 1.6 BLUEHDI EAT6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU7473U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*REAR BUMPER	Dented	1,120.00 FS	*1,120.00 FS
3	1		*BUMPER BRACKET	Dented	338.00 FS	*338.00 FS
4	1		*BUMPER SKIRT	Cut	370.00 FS	*370.00 FS
5	1		*RECESS DOOR	Missing	72.00 FS	*72.00 FS
6	1		*SET BRACKET	Necessary	138.00 FS	*138.00 FS
7	1		*BRACKET SET LAT	Not Necessary	138.00 FS	*- FS
8	1		*BUMPER SEAL	Not Necessary	52.00 FS	*- FS
9	1		*BUMPER BRACKET	Broken	334.00 FS	*334.00 FS
10	1		*ANGLE PLATE	Not Necessary	56.00 FS	*- FS
11	1		*STIFFRNER LH	Not Necessary	100.00 FS	*- FS
12	1		*STIFFRNER RH	Not Necessary	100.00 FS	*- FS
13	1		*BUMPER BRACKET	Not Necessary	90.00 FS	*- FS
14	1		*LOW RR PAN FIX	Necessary	168.00 FS	*168.00 FS
15	1		*SENSOR SUPPORT	Necessary	160.00 FS	*160.00 FS
16	2		*SENSOR	Not Necessary	382.00 FS	*- FS
17	2		*SENSOR	Not Necessary	540.00 FS	*- FS
18	4		*SENSOR SUPPORT	Not Necessary	640.00 FS	*- FS
19	1		*REAR LICENSE PLATE WITH FRAME	Cut	60.00 FS	*60.00 FS
20	1		*C&C LOGO	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **4,958.00** **2,830.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER FACE ,REPAIR REAR END PANEL	New	2,280.00	760.00
2	REMOVE AND INSTALL PARKING ASSIST	New	120.00	120.00
3	PAINT WORK SPRAY REAR END PANEL,REAR BUMPER AND AFFECTED PORTION	New	1,650.00	1,100.00
4	PERFORM RUST PREVENTION	New	80.00	0.00
5	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	50.00	50.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	380.00	380.00
Gross Labour Cost (S\$)			4,560.00	2,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >