



S THREE AUTOMOTIVE RECOVERY PTE LTD

Not Authorized  
L1 Reg @ 5600ph  
Penalty After Rain

TO :  
ATTN : MOTOR CLAIM DEPT.

T/P VEH. NO. : XD2226Y

ESTIMATE REPORT 1st QUOTATION

JOB NO. : \_\_\_\_\_

OWNER'S PARTICULAR

NAME : SURPASS AUTO PARTS SUPPLIES PTE LTD  
ADDRESS :

CONTACT :

LICENSE NO. GBK4282U

TRANS. :

CHASSIS NO. KPADA1EESJP329646

MAKE / MODEL : SSANGYONG ACTYON

ENGINE NO. :

OWNER'S INSURER : LIBERTY INSURANCE

JOB-CODE : TP

S/A : MICHELLE

ACCIDENT DATE : 01-Mar-21

## CLAIM DETAIL

## MATERIALS

|                                       | QTY  | QUO-PRICE | DISC. % | DISC. PRICE | SUR. REV. PRICE |   |
|---------------------------------------|------|-----------|---------|-------------|-----------------|---|
| 1 REAR TAIL GATE                      | 1.00 | 2650      | 10.00   |             | Y 2385          | ✓ |
| 2 REAR TAIL GATE LOCK RH              | 1.00 | 320       | 10.00   | 11          | Y 281           | X |
| 3 REAR TAIL GATE LOCK LH              | 1.00 | 320       | 10.00   | 11          | Y 281           | X |
| 4 REAR TAIL GATE HINGE LH             | 1.00 | 285       | 10.00   | 017         | Y 256.50        | 7 |
| 5 REAR TAIL GATE HINGE RH             | 1.00 | 285       | 10.00   | 017         | Y 256.50        | 7 |
| 6 REAR TAIL GATE EMBLEM SSANGYONG     | 1.00 | 150       | 10.00   | 11          | Y 135           | ✓ |
| 7 REAR TAIL GATE EMBLEM ACTYON SPORTS | 1.00 | 150       | 10.00   | 11          | Y 135           | ✓ |
| 8 REAR TAIL GATE LOGO                 | 1.00 | 120       | 10.00   | 11          | Y 108           | ✓ |
| 9 REAR TAIL GATE INNER TRIM           | 1.00 | 630       | 10.00   | 11          | Y 567           | 7 |
| 10 REAR END PANEL                     | 1.00 | 1280      | 10.00   | 11          | Y 1150          | X |
| 11 REAR DOOR LH                       | 1.00 | 1950      | 10.00   | 11          | Y               | ✓ |
| 12 REAR FENDER LH                     | 1.00 | 220       | 10.00   | 11          | Y               | X |
| 13 REAR BUMPER                        | 1.00 | 220       | 10.00   | 11          | Y               | ✓ |
| 14 REAR BUMPER REFLECTOR LH           | 1.00 | 230       | 10.00   | 11          | Y               | ✓ |
| 15 REAR BUMPER REFLECTOR RH           | 1.00 | 230       | 10.00   | 11          | Y               | ✓ |
| 16 REAR BUMPER BRACKET LH             | 1.00 | 890       | 10.00   | 11          | Y               | X |
| 17 REAR BUMPER BRACKET RH             | 1.00 | 110       | 10.00   | 11          | Y               | X |
| 18 REAR BUMPER REINFORCEMENT          | 1.00 | 110       | 10.00   | 11          | Y               | X |
| 19 REAR NO. PLATE LAMP LH             | 1.00 | 450       | 10.00   | 11          | Y               | X |
| 20 REAR NO. PLATE LAMP RH             | 1.00 | 450       | 10.00   | 11          | Y               | X |
| 21 TAIL LAMP LH                       | 1.00 | 2850      | 10.00   | 11          | Y               | ✓ |
| 22 TAIL LAMP RH                       | 1.00 | 2950      | 10.00   | 11          | Y               | X |

TOTAL (PARTS) :

\$ - \$ -

## SPECIAL NETT ITEM

|                               |      |         |      |         |   |       |
|-------------------------------|------|---------|------|---------|---|-------|
| 1 REAR BUMPER CLIPS -1SET     | 1.00 | 1280.00 | 0.00 | 1280.00 | Y | 30Jan |
| 2 REAR BUMPER PROTECTOR -1SET | 1.00 | 20.00   | 0.00 | 20.00   | Y | X     |
| 3 REAR NUMBER PLATE           | 1.00 | 20.00   | 0.00 | 20.00   | Y | X     |
| 4 REAR END PANEL SEALANT      | 1.00 | 120.00  | 0.00 | 120.00  | Y | X     |
| 5 REAR TAIL GATE STICKER 70KM | 1.00 | 50.00   | 0.00 | 50.00   | Y | 12Jan |

6 REAR FENDER INNER TRIMBOARD CLIPS 1.00 *nn* 80.00 0.00 80.00 Y X

1570.00 1570.00

TOTAL (PARTS):

LABOUR

|   |                                          |      |                  |      |         |   |             |
|---|------------------------------------------|------|------------------|------|---------|---|-------------|
| 1 | STRAIGHTEN & PANEL BEAT ON ACCIDENT AREA | 1.00 | 1600.00          | 0.00 | 1600.00 | Y | <u>6001</u> |
| 2 | SPRAY PAINT ON ACCIDENT AREA             | 1.00 | 1600.00          | 0.00 | 1600.00 | Y | <u>8001</u> |
| 3 | CHECK & REPAIR WIRING SYSTEM             | 1.00 | 120.00           | 0.00 | 120.00  | Y | <u>201</u>  |
| 4 | R&R TAILGATE SYSTEM                      | 1.00 | 150.00           | 0.00 | 150.00  | Y | <u>501</u>  |
| 5 | R&R CABIN TO ASSIST REPAIR               | 1.00 | <i>nn</i> 380.00 | 0.00 | 380.00  | Y | <u>X</u>    |
| 6 | RESPRAY TUFF KOTE ON AFFECTED AREA       | 1.00 | 150.00           | 0.00 | 150.00  | Y | <u>801</u>  |
| 7 | CONDUCT CHASSIS ALIGNMENT                | 1.00 | <i>nn</i> 380.00 | 0.00 | 380.00  | Y | <u>X</u>    |

4380.00 4380.00

TOTAL (LABOUR):

5950.00 5950.00

TOTAL PARTS & LABOUR

EXCESS:

: S\$ \_\_\_\_\_

NO. OF DAY

: 05 days

RE-SURVEY: ~~BEFORE~~ / AFTER PAINTING

PART ~~BY~~-PART OR LUMP-SUM

DATE OF SURVEY

: 8 / 3 / 21

SURVEY BY

: Kenroth

CONTACT NO

FAX NO

NOTE: LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.





# S THREE AUTOMOTIVE RECOVERY PTE LTD

TO :  
ATTN : MOTOR CLAIM DEPT.

T/P VEH. NO. : XD2226Y

ESTIMATE REPORT 1st QUOTATION  
OWNER'S PARTICULAR

JOB NO. : \_\_\_\_\_

NAME : SURPASS AUTO PARTS SUPPLIES PTE LTD  
ADDRESS : \_\_\_\_\_

CONTACT : \_\_\_\_\_

LICENSE NO. GBK4282U  
MAKE / MODEL : SSANGYONG ACTYON  
OWNER'S INSURER : LIBERTY INSURANCE  
JOB-CODE : TP

TRANS. :  
S/A : MICHELLE

CHASSIS NO. : KPADA1EESJP329646  
ENGINE NO. : \_\_\_\_\_

ACCIDENT DATE : 01-Mar-21

## SUPPLEMENTARY ITEMS

### MATERIALS

|                                | QTY  | QUO-PRICE   | DISC. % | DISC-PRICE  | SUR. DISP | REV. PRICE |
|--------------------------------|------|-------------|---------|-------------|-----------|------------|
| 1 REAR OUTER HANDLE 290        | 1.00 | \$ 428.00   | 10.00   | \$ 470.80   | Y         | ✓          |
| 2 REAR TAIL GATE CABLE RH      | 1.00 | \$ 280.00   | 10.00   | \$ 308.00   | Y         | X          |
| 3 REAR TAIL GATE CABLE LH 196  | 1.00 | \$ 280.00   | 10.00   | \$ 308.00   | Y         | ✓          |
| 4 REAR CABIN GARNISH (PLASTIC) | 1.00 | \$ 1,480.00 | 10.00   | \$ 1,628.00 | Y         | X          |
| TOTAL (PARTS) :                |      | \$ 2,468.00 |         | \$ 2,714.80 |           |            |

### SPECIAL NETT ITEM

|                                  |      |           |      |           |   |   |
|----------------------------------|------|-----------|------|-----------|---|---|
| 1 REAR CABIN GARNISH CLIPS -1SET | 1.00 | 160.00    | 0.00 | 160.00    | Y | X |
| TOTAL (PARTS) :                  |      | \$ 160.00 |      | \$ 160.00 |   |   |

EXCESS :  
NO. OF DAY : SS  
RE-SURVEY : BEFORE / AFTER PAINTING  
PART-BY-PART OR LUMP-SUM  
DATE OF SURVEY : \_\_\_\_/\_\_\_\_/\_\_\_\_  
SURVEY BY : \_\_\_\_\_  
CONTACT NO : \_\_\_\_\_  
NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

FAX NO : \_\_\_\_\_

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_