



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623		Ref: CS/SMO21002825/BKtd3e2 Date: 06/04/2021 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJL 8812P	Veh. Inspected	YP 9412E
Policy No.	D20MTPV01005043	Coverage (\$)	0.00
Claim No.	CMTD2100661/IJH	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	02/03/2021
2. Vehicle Particulars & Condition			
Make & Model	HINO XZU710R	c.c	4009
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JHHUCV1H60K028042	Colour	WHITE
Odometer	72311 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/85 R16	TRA02	6 mm
L/H Front Tyre	215/85 R16	TRA02	6 mm
R/H Rear Tyre	7.00 R16	TR668	6 mm
L/H Rear Tyre	7.00 R16	TR668	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	28/02/2021	Inspection Date	03/03/2021
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	