



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4651D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	PANEL ASSY-REAR DOOR LH	TO REPAIR SEE LABOUR	1,789.90	-
1	MOULDING ASSY-W/LINE RR D	TO REPAIR SEE LABOUR	166.20	-
1	MIRROR ASSY-OUTSIDE RR VI	TO REPAIR SEE LABOUR	1,391.70	-
	LESS 20% DISCOUNT		-669.56	-
			2,678.24	-
	<b><u>NETT ITEMS</u></b>			
1	APP LOGO REAR DOOR L/R CT (N)	CUT	80.00	80.00
	LESS 10% DISCOUNT		-8.00	-8.00
			72.00	72.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING (REPAIR RR FENDER LH).INCLUSIVE OF THE REPAIR OF PANEL ASSY-REAR DOOR LH,MOULDING ASSY-W/LINE RR D AND MIRROR ASSY-OUTSIDE RR VI.		600.00	525.00
	SPRAYPAINT ON AFFECTED AREA.		550.00	500.00
	TRANSFER OF DOOR REAR LH.	NOT NECESSARY	120.00	-
			1,270.00	1,025.00
	<b>GRAND TOTAL</b>		<b>4,020.24</b>	<b>1,097.00</b>
<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>				<b>1,097.00</b>

Report Ref No. NS/INC21002831/T1qd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.