



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref: CS3/SMO21000908/QKtd3e2-1

50 RAFFLES PLACE #03-03
SINGAPORE LAND TOWERSINGAPORE 048623

Date: 12/04/2021

Code: SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMF 953P	Veh. Inspected	SMW 1313R
Policy No.	D20MTPV01013212	Coverage (\$)	0.00
Claim No.	CMTD2100207/GPL	Excess (\$)	0.00
Assign From	GNOH PAU LOONG	Assign Date	02/03/2021

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ E200	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WDD2130422A043271	Colour	BLACK
Odometer	222706 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/45 R18	GOODYEAR	6 mm
L/H Front Tyre	245/45 R18	GOODYEAR	6 mm
R/H Rear Tyre	245/45 R18	GOODYEAR	6 mm
L/H Rear Tyre	245/45 R18	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/01/2021	Inspection Date	19/01/2021
Survey held at	60 JALAN LAM HUAT, #07-35/36		
Repairer	WELLTAC AUTO SPRAY CENTRE		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**