

ALLSWELL MOTOR TRADERS

Unit Lane 9, Singapore 539266

Reg No.: 53192889J

No.: 6679 1146 / 91478545

Email: ben@allswellmotor.com.sg

account5@allswellmotor.com.sg

(3rd Party Claim Against AIG Insured SMY794G)

DOA: 26.02.2021

Repair Estimate

Vehicle No. : SUR46632

Submitted by : Bw

Make & Model : Alpha Prime Toyota

COE Expiry : 15.08.2027

S/No	Part Description	Qty	Price	Unit Price	Disposition by
01a	End panel ?	01	\$795.00		
01	Tailgate / Rec	01	\$980.00		
02	rear bumper / Rec	01	\$1,315.00		
03	LH retainer / X Rec	01	\$55.00		
04	RH retainer / Rec	01	\$55.00		
05	End panel top garnish	01	\$179.00		
06	Keyless sender ?	01	\$240.00		
07	Windscreen moulding x 2 / Rec	01	\$185.00		
Special mlt					
01	Windscreen sealant / Rec	01	\$60.00		
02	Clips / retainer studs for bumper, / Rec tailgate back garnish, end panel top garnish & etc	01	\$45.00		
Labour Description					
01	Remove / Refix windscreen rear	01	\$150.00	100	
02	Dismantle / assembly of all affected parts	01	\$400.00	✓	
03	Spray paint, tailgate 2x, bumper, fender x2	01	\$800.00	600	

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Acknowledged by Repairer
Signature: _____
Date: _____

4 Days.
Imps in repair
After repair photos.
Ch. Rieng 23/3/21