



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJM 5329H

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R



MOTOR SURVEYOR ACKNOWLEDGEMENT FORM	
Vehicle Number : 5329H Date of Accident : 3/12/11	
PRE-REPAIR INSPECTION (PRE)	
Insurance Company : LKK	
Name of Surveyor : T. S. L. L. L.	
Date & Time of Survey : 3/12/11 07:58	
FOLLOW-UP INSPECTION (FOR RESURVEY OF DAMAGED/HIDDEN PARTS)	
Name of Surveyor :	
Date & Time of Survey :	
REINSPECTION OF NEW REPLACEMENT PART (PART BY PART)	
Name of Surveyor :	
Date & Time of Survey :	
FINAL INSPECTION (COMPLETION OF REPAIR)	
Name of Surveyor :	
Date & Time of Survey :	