



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
Mr Azman Bin Sahari Blk 602 Choa Chu Kang St 62 #04-35 Singapore 680602 Contact No	Cust No/Name KCV05720/Azman Bin Sahari Reg No/Reg Date SLF2601D / 19/08/201 Date In/Mileage / 0 Chassis No JMYXTGF3WGJ000808 Engine No 4B12RS2843 Make/Model MIT/OUTLANDER 2.4 CVT AWD (G43) Colour/Trim D01 COSMIC BLUE MIC/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KCV05720	CRDVCH	16/02/2021/ 14:55	TLC	442 / CocoLu	62945

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW TAILGATE, REPAIR REAR BUMPER, TAILGATE GARNISH	2 X 640			1280.00
E PNT98000 SPRAY PAINT FOR REAR BUMPER, TAILGATE, TAILGATE GARNISH	2 X 550			1100.00
E PNT88000 REMOVE & INSTALL TAILGATE GLASS				300.00
M SUNDRY APPLY SEALANT FOR TAILGATE GLASS				80.00
M SUNDRY APPLY SEALANT FOR ACCIDENT PORTION				40.00
M SUNDRY Sundry				20.00
M SUNDRY C&C LOGO				40.00
E PNT88000 REMOVE & INSTALL TAILGATE TRIMS				200.00
M PANEL ASSY, TAILGATE	1.00	984.00	00.00	984.00
M DAM, TAILGATE, LWR	1.00	41.00	00.00	41.00
M STOPPER, WINDSHIELD GLASS	2.00	3.00	00.00	6.00
M DAM, TAILGATE SIDE	2.00	27.00	00.00	54.00
M FASTENER, WINDSHIELD	4.00	6.00	00.00	24.00
M DAM, TAILGATE, UPR	1.00	13.00	00.00	13.00
M MARK, OUTLANDER	1.00	95.00	00.00	95.00
M DECAL, 4WD	1.00	18.00	00.00	18.00

Estimate

Store (LKK) with Part
8/3/21, 2.10pm
5 days
P/P

My B&L Sign

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm & accepted by

Authorized signatory and company stamp

7% GST on **Nett** 4,295.00
300.65
Total Payable 4,595.65

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.