

Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Azman Bin Sahari Blk 602 Choa Chu Kang St 62 #04-35 Singapore 680602 Contact No	Cust No/Name KCV05720/Azman Bin Sahari Reg No/Reg Date SLF2601D / 19/08/201 Date In/Mileage / 0 Chassis No JMYXTGF3WGJ000808 Engine No 4B12RS2843 Make/Model MIT/OUTLANDER 2.4 CVT AWD (G43) Colour/Trim D01 COSMIC BLUE MIC/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KCV05720	CRDVCH	16/02/2021/ 14:55	TLC	442 / CocoLu	62945

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW TAILGATE, REPAIR REAR BUMPER, TAILGATE GARNISH	2 X 640			1280.00 ✓
E PNT98000 SPRAY PAINT FOR REAR BUMPER, TAILGATE, TAILGATE GARNISH	25X 550			13750.00 ✓
E PNT88000 REMOVE & INSTALL TAILGATE GLASS				80.00 ✓
M SUNDRY APPLY SEALANT FOR TAILGATE GLASS				40.00 ✓
M SUNDRY APPLY SEALANT FOR ACCIDENT PORTION				20.00 ✓
M SUNDRY Sundry				40.00 ✓
M SUNDRY C&C LOGO				200.00 ✓
E PNT88000 REMOVE & INSTALL TAILGATE TRIMS	1.00	989	984.00 00.00	984.00 ✓
M PANEL ASSY, TAILGATE	1.00	41.00	00.00	41.00 ✓
M DAM, TAILGATE, LWR	2.00	3.00	00.00	6.00 ✓
M STOPPER, WINDSHIELD GLASS	2.00	27.00	00.00	54.00 ✓
M DAM, TAILGATE SIDE	4.00	6.00	00.00	24.00 ✓
M FASTENER, WINDSHIELD	1.00	13.00	00.00	13.00 ✓
M DAM, TAILGATE, UPR	1.00	95.00	00.00	95.00 ✓
M MARK, OUTLANDER	1.00	18.00	00.00	18.00 ✓
M DECAL, 4WD				

Estimate

*Store (LKK) with Part
8/3/21, 2.10pm
5 days
P/P*

LKK Auto Consultants hence notify the Repairer of the following:

• To resurvey before/after spray painting

• To display damaged part(s) during resurvey

• Prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm & accepted by

7% GST on	Nett 4295.00	4,295.00
		300.65
Total Payable		4,595.65

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

INSURANCE CO. : LONPAC

Supplementary For Registration No.: SLF 2601 D

<u>Materials</u>		<u>Cost \$</u>
1	Mark, Three- DIA	61.00 / nec
2	Face, RR Bumper	811.00 / DD
		<u>872.00</u>
<u>Labour</u>		
1	Check Wiring & Chassis Electrical System	30.00 /
2	To Carry Out Diagnostic Check Using Hi-Scan Pro Test	120.00 /
		<u>150.00</u>
Labour & Materials		1,022.00
7% GST		71.54
Total		<u>1,093.54</u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens