

## **LKK Auto Consultants Pte Ltd**

LKK Auto Consultants Fte L
51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMV 9479Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
12	FRONT BUMPER CLIPS @\$9.00	NECESSARY	108.00	30.00
12	FRONT BUMPER RIVETS @\$9.00	NECESSARY	108.00	30.00
1	FRONT BUMPER CORE (LONG)	CRUMPLED	155.00	155.00
1	FRONT BUMPER CORE (SHORT)	CRUMPLED	142.00	142.00
1	FRONT BUMPER SPONGE (CENTER)	CRUMPLED	250.00	250.00
2	FRONT BUMPER SPONGE (SIDE) @\$95.00	CRUMPLED	190.00	190.00
1	FRONT BUMPER NUMBER PLATE HOLDER	SERVICEABLE	115.00	-
1	GRILLE (MAYBACH)	DEFORMED	7,880.00	2,050.00
1	FRONT GRILLE HANDLE PULL	CRUMPLED	105.00	105.00
1	HEADLAMP (HID) RH	CRACKED	4,110.00	3,659.12
	LESS 5% DISCOUNT		-658.15	-330.56
			12,504.85	6,280.56
	SPECIAL NETT ITEMS			
1	FRONT BUMPER (WALD BLACK BISON EDITION)(SN)	CRACKED	3,500.00	2,500.00
1	FRONT NUMBER PLATE (CHROME)(SN)	CRACKED	120.00	70.00
1	FRONT BUMPER PARKING ELECTROMAGNETOC SENSOR (SN)	NECESSARY	450.00	450.00
1	FRONT BUMPER EMBLEM "COMPETITIVE" (SN)	NECESSARY	110.00	90.00
1	FRONT BUMPER LOGO "MOTORSPORT" (SN)	NECESSARY	50.00	50.00
			4,230.00	3,160.00
	<u>LABOUR</u>			
	TO CONDUCT ELECTRICAL CHECK, FOCUS HEADLAMP.		30.00	30.00
	LABOUR CHARGE-PANEL BEATING,REPAIRING OF BONNET,SUPPORT PANEL AND PARTS REPLACEMENT.		400.00	300.00
	TO RESPRAY AFFECTED AREAS.		600.00	400.00
			1,030.00	730.00
	GRAND TOTAL		17,764.85	10,170.56

Report Ref No. CS/AGI21002847/Qvd3n2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	8,100.00
(TO ITS PRE-ACCIDENT CONDITION)	·

Report Ref No. CS/AGI21002847/Qvd3n2

Ja

OI SUN PIN

**Asst. Automotive Assessor** 

X.S.

**ADRIAN LING WAI PING** 

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

**Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.