



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2102095

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 30/03/2021
Reference CS3/GRB21002855/R1td3e2
Code GRB

PROFESSIONAL SERVICE FEE

Vehicle No. SLQ 6033J
Insured Veh. SLX 781K
Claim No. MFL2021D0000944
Policy No. D21MFL0000447
Accident Date 01/03/2021
Inspection Date 05/03/2021

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
- First Inspection 05.03.2021 09.49am	
- Dismantle Inspection 08.03.2021 1140am	
- After Repair Inspection 16.03.2021 09.15am	
Merimen Fee	11.00
Subtotal	131.00
GST (7%)	9.17
Grand Total	140.17

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM