



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21002858/AUvf3n2	
			Date: 01/07/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	FBR 1862D	Veh. Inspected	SK 3000Y
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2100675/MYE	Excess (\$)	0.00
	Assign From	GARCE TEO	Assign Date	02/03/2021
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ 230CE	c.c	2298
	Engine No.	HIDDEN	Year of Reg.	1992
	Chassis No.	WDB1240432B669176	Colour	SILVER
	Odometer	342688 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	KENDA	6 mm
	L/H Front Tyre	195/65 R15	KENDA	6 mm
	R/H Rear Tyre	195/65 R15	KENDA	6 mm
	L/H Rear Tyre	195/65 R15	KENDA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	01/03/2021	Inspection Date	03/03/2021
	Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	