

A T AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113

HP: 8386 8989

Co. Reg. No. : 53368526E

Date of Estimate: 02.03.2021

Vehicle No: SLZ5160J

Owner: PILOT NETWORK PTE LTD

Date of Accident: 01.03.2021

Make & Model: HONDA SHUTTLE

Chassis No : GP71209856

Not Authorized
6/1/21 @
Murray After Pairs
4-5 days

ESTIMATE FOR ACCIDENT VEHICLE NO SLZ5160J

PARTS

1	1	Tailgate
2	1	Tailgate lock
3	1	Tailgate windscreen moulding
4	1	Tailgate chrome moulding
5	1	Tailgate weather strip
6	1	Tailgate emblem "HONDA"
7	1	Tailgate emblem "SHUTTLE"
8	1	Tailgate emblem "HYBRID"
9	1	Rear bumper
10	2	Rear bumper side retainer LH/RH
11	1	Rear bumper reflector LH/RH
12	1	Rear end panel
13	1	Rear end panel top garnish
14	1	Remote key buzzer
15	1	Remote key buzzer bracket

@ \$48
@ \$49

By	\$1,293.33	✓
1	\$186.30	X
2	\$85.00	✓
3	\$393.30	X
4	\$286.00	X
5	\$86.00	✓
6	\$85.00	✓
7	\$56.00	✓
8	\$1,225.00	✓
9	\$96.00	X
10	\$98.00	X
11	\$588.00	?
12	\$198.00	?
13	\$88.00	?
14	\$18.00	?

SUB TOTAL \$4,781.93
LESS 10 % \$513.40
DISCOUNTED SUB TOTAL \$4,268.53

S. NETT ITEM

1	1set	Rear bumper clips
2	1set	Reverse sensor
3	1set	Reverse camera

SUB TOTAL \$720.00
LESS 0 % \$0.00
DISCOUNTED SUB TOTAL \$720.00

1	\$50.00	✓
2	\$320.00	?
3	\$350.00	X
SUB TOTAL	\$720.00	
LESS 0 %	\$0.00	
DISCOUNTED SUB TOTAL	\$720.00	

LABOUR

1	Panel beating for replace and repair affected parts
2	Spray painting on accident areas
3	Wiring charges
4	Remove/refix reverse sensor
5	Remove/refix reverse camera
6	Transfer tailgate glass
7	Transfer tailgate component
8	Apply undercoating to above affected areas

SUB TOTAL (LABOUR)

\$800.00	?
\$800.00	60d
\$100.00	15%
\$100.00	50d
\$100.00	50d
\$200.00	120d
\$150.00	60d
\$120.00	?

\$2,370.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: