

A T AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113

HP: 8386 8989

Co. Reg. No. : 53368526E

Date of Estimate: 02.03.2021

Vehicle No: SLZ5160J

Owner: PILOT NETWORK PTE LTD

Date of Accident: 01.03.2021

Make & Model: HONDA SHUTTLE

Chassis No : GP71209856

Not Authorized
11pm @ 1850h
Money After Paim
& days

ESTIMATE FOR ACCIDENT VEHICLE NO SLZ5160J

PARTS

1	1	Tailgate
2	1	Tailgate lock
3	1	Tailgate windscreen moulding
4	1	Tailgate chrome moulding
5	1	Tailgate weather strip
6	1	Tailgate emblem "HONDA"
7	1	Tailgate emblem "SHUTTLE"
8	1	Tailgate emblem "HYBRID"
9	1	Rear bumper 950
10	2	Rear bumper side retainer LH/RH
11	1	Rear bumper reflector LH/RH
12	1	Rear end panel
13	1	Rear end panel top garnish
14	1	Remote key buzzer
15	1	Remote key buzzer bracket

SUB TOTAL
LESS 10% **20%**
DISCOUNTED SUB TOTAL

R	B	\$1,293.33	X
R	B	\$186.30	X
nn	na	\$85.00	wa X
nn	na	\$393.30	X
nn	na	\$286.00	X
nn	na	\$86.00	—
nn	na	\$85.00	—
nn	na	\$56.00	—
B	na	\$1,225.00	—
nn	na	\$96.00	X
nn	na	\$98.00	X
nn	na	\$588.00	X
nn	na	\$198.00	X
nn	na	\$88.00	X
nn	na	\$18.00	X
		\$4,781.93	
		\$513.40	
		\$4,268.53	

S. NETT ITEM

1	1set	Rear bumper clips
2	1set	Reverse sensor
3	1set	Reverse camera

SUB TOTAL
LESS 0 %
DISCOUNTED SUB TOTAL

nn	\$50.00	—
shar	\$320.00	2000n
nn	\$350.00	X
		\$720.00
		\$0.00
		\$720.00

LABOUR

1	Panel beating for replace and repair affected parts
2	Spray painting on accident areas
3	Wiring charges
4	Remove/refix reverse sensor
5	Remove/refix reverse camera
6	Transfer tailgate glass
7	Transfer tailgate component
8	Apply undercoating to above affected areas

SUB TOTAL (LABOUR)

	\$800.00	40d
	\$800.00	60d
	\$100.00	15h
	\$100.00	50d
	\$100.00	50d
nn	\$200.00	120X
nn	\$150.00	60X
nn	\$120.00	X
		\$2,370.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: