



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883

Company GST Registration No : 201828067M

VEHICLE INSPECTION ESTIMATE

M/S : Budget Direct Insurance
(MOTOR CLAIM DEPARTMENT)

Email claims@gudgetdirect.com.sg

Parts - (%)

SN

Labour

Lump sum

ERV

Denise.

Vehicle No: SMK3321S

Date: 02.03.2021

Veh Model : HYUNDAI ACCENT

Reg Date : 05.04.2019

Chassis No : KMHCU41BTKU464880

D.O.A : 28.02.2021

1	Front Bumper <i>Repair</i>	1		+ 548.50
2	Front Bumper Retainer LH <i>New</i>	1		+ 79.60
3	Front Fender LH <i>Distorted</i>	1		✓ 647.40
4	Front Fender Cowling LH <i>torn</i>	1		✓ 156.70
5	Side Mirror Assy <i>Repair</i>	1		✓ 758.90
6	Side Mirror Signal Lamp LH <i>cracked</i>	1		✓ 137.30
7	Side Mirror Back Cover <i>Repair</i>	1		+ 76.30
8	Front Door LH <i>Distorted</i>	1		✓ 1,298.50
9	Front Door Hinges LH <i>2 piece bend</i>	2	69.80	69.80 139.60
10	Front Door Checker LH <i>New</i>	1		+ 68.90
11	Front Door Lock LH <i>NP</i>	1		+ 184.00
12	Front Door Latch LH <i>NP</i>	1		+ 80.60
13	Front Door Stoppers <i>New</i>	1		+ 33.70
14	Front Door Stickers LH <i>New</i>	2	28.60	✓ 57.20
15	Front Door Outer Handle LH <i>New</i>	1		+ 145.60
16	Front Door Outer Handle Knob LH <i>?</i>	1		+ 34.50
17	Front Door Outer Moulding LH <i>NP</i>	1		+ 67.40
18	Front Door Weatherstrip LH <i>NP</i>	1		+ 90.10
19	Front Door Frame Weatherstrip LH <i>NP</i>	1		+ 87.80

4,692.60

CF

4,692.60



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883

Company GST Registration No : 201828067M

VEHICLE INSPECTION ESTIMATE

B/F

4,692.60

20	Front Door Trim Board LH <i>new</i>	1		<i>x</i> 546.10
21	Front Door Window Regulator <i>3 new</i>	1		<i>+</i> 99.20
22	Front Door Window Regulator Motor <i>new</i>	1		<i>+</i> 406.90
23	Front Door Window Run Channel LH <i>new</i>	1		<i>+</i> 156.20
24	Front Shock Absorber LH <i>new</i>	1		<i>+</i> 397.50
25	Front Shock Absorber Top Mounting LH <i>new</i>	1		<i>+</i> 78.50
26	Front Knuckle Arm LH <i>3 new</i>	1		<i>+</i> 402.30
27	Front Lower Arm LH <i>new</i>	1		<i>+</i> 345.20
28	Front Stabilizer Link LH	1		<i>+</i> 98.60
29	Front Wheel Bearing W Hub LH <i>new</i>	1		<i>+</i> 398.70
30	Rim <i>new</i>	1		<i>+</i> 203.30

7,825.10

3125.80

less 20%

1,565.02

2500.64

6,260.08

Special nett item

1	Front Fender Cowling Clips <i>new</i>	1 set		<i>✓</i> 30.00
---	---------------------------------------	-------	--	----------------

30

To panel beat/straighten/realign accident affected portion.	<i>600</i> 1,200.00
To respray accident affected portion.	<i>700</i> 1,200.00
To tuff coat affected areas.	<i>50</i> 120.00
To conduct wiring check and repair	<i>1460</i> 30 100.00
To conduct water leak test.	<i>+</i> 100.00
To remove/transfer door mechanism	<i>80</i> 150.00
	9,160.08

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Adrian King

1/s 03/03/21

05 Pys

total: 3990.64

1/s: 3.2K.