

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

AIG

Owner : Mohammad Nur Khairul Bin
Ahmad

Accident Date : 19-Feb-21

Vehicle No : FBE5706P

Vehicle Model : Yamaha X-1R

Estimated Repair Costs

Qty	Description	Amount S(\$)
<u>List Items</u>		
1	Front fork assy	\$ 640.00
1	Fork under bracket <i>ny X</i>	\$ 200.00
1	Front fender <i>cut ✓</i>	\$ 80.00
1	Front rim <i>ny X</i>	\$ 260.00
1	Front brake disc <i>ny X</i>	\$ 145.00
1	Front rim shaft <i>cut ✓</i>	\$ 45.00
1	Headlamp <i>ny X</i>	\$ 180.00
1	Side mirror (1 set) <i>ny ✓</i>	\$ 110.00
1	Front signal - R/H <i>cut ✓</i>	\$ 90.00
1	Handle bar <i>?</i>	\$ 85.00
1	Handle-bar grip (1 set) <i>worn ✓</i>	\$ 85.00
1	Handle front cover <i>ny X</i>	\$ 85.00
1	Brake lever <i>cut ✓</i>	\$ 32.00
1	Front footrest rubber <i>worn ✓</i>	\$ 50.00
1	Front footrest bracket <i>cut ✓</i>	\$ 120.00
1	Brake pedal <i>ny X</i>	\$ 60.00
1	Top cover <i>cut ✓</i>	\$ 120.00
1	Front side cover - R/H <i>cut ✓</i>	\$ 175.00
1	Front inner center cover (key side) <i>ny X</i>	\$ 120.00
1	Rear footrest - R/H <i>cut ✓</i>	\$ 28.00
1	Rear handle <i>ny X</i>	\$ 180.00
1	Engine cover <i>cut ny X</i>	\$ 480.00
1	Engine cover gasket <i>ny X</i>	\$ 75.00
1	Exhaust cover <i>cut ✓</i>	\$ 120.00
1	Master pump <i>Damage ✓</i>	\$ 480.00
		\$ 4,045.00
<i>not Arthur</i>		Less 10%
		\$ 404.50
		\$ 3,640.50

not Arthur
all

3/3/21

L/S \$
Zhe pte. Hwa rep

Hdys

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : Mohammad Nur Khairul Bin
Ahmad

Accident Date : 19-Feb-21

Vehicle No : FBE5706P

Vehicle Model : Yamaha X-1R


Estimated Repair Costs

<u>Special Net Items</u>			
1	Number plate - (1 set) <i>for 10</i>	\$	28.00 <i>10</i>
2	Fork oils <i>11x</i>	\$	30.00 <i>x</i>
2	Fork oil seals <i>11x</i>	\$	56.00 <i>x</i>
1	Steering cone (1 set) <i>11x</i>	\$	75.00 <i>60</i>
1	Engine oil <i>11x</i>	\$	35.00 <i>x</i>
1	E.R.P. IU <i>11x</i>	\$	180.00 <i>x</i>
1	Rear box <i>11x</i>	\$	150.00 <i>x</i>
1	Rear box bracket <i>11x</i>	\$	380.00 <i>180</i>
		\$	<u>934.00</u>

<u>S/No.</u>	<u>Labour</u>		
1	To provide towing service	\$	30.00 <i>25</i>
2	To remove, refit and align front fork tubes	\$	11 180.00 <i>x</i>
3	To check electrical and headlamp focusing	\$	11 80.00 <i>x</i>
4	To provide paint work	\$	580.00 <i>400</i>
5	To provide labour	\$	420.00 <i>250</i>
		\$	<u>1,290.00</u>

Grand Total \$ 5,864.50

Singapore Dollars: Five Thousand Eight Hundred Sixty-Four and Cents: Fifty only



EROFIA MOTOR TRADING PTE LTD

Link Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prajudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: