

# EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

AIG

Owner : Mohammad Nur Khairul Bin Ahmad

Accident Date : 19-Feb-21

Vehicle No : FBE5706P

Vehicle Model : Yamaha X-1R

## Estimated Repair Costs

Qty	Description	Amount S(\$)
<u>List Items</u>		
1	Front fork assy <span style="float: right;">Seat (TWT) ✓</span>	\$ 640.00 ✓
1	Fork under bracket <span style="float: right;">17 X</span>	\$ 200.00 X
1	Front fender <span style="float: right;">cut ✓</span>	\$ 80.00 ✓
1	Front rim <span style="float: right;">17 X</span>	\$ 260.00 X
1	Front brake disc <span style="float: right;">17 X</span>	\$ 145.00 X
1	Front rim shaft <span style="float: right;">cut ✓</span>	\$ 45.00 ✓
1	Headlamp <span style="float: right;">17 X</span>	\$ 180.00 X
1	Side mirror (1 set) <span style="float: right;">ols 320 ✓</span>	\$ 110.00 ✓
1	Front signal - R/H <span style="float: right;">ols 60 ✓</span>	\$ 90.00 ✓
1	Handle bar <span style="float: right;">ols Seat ✓</span>	\$ 85.00 ✓
1	Handle-bar grip (1 set) <span style="float: right;">Torn ✓</span>	\$ 85.00 ✓
1	Handle front cover <span style="float: right;">RX</span>	\$ 85.00 X
1	Brake lever <span style="float: right;">cut ✓</span>	\$ 32.00 ✓
1	Front footrest rubber <span style="float: right;">Torn ✓</span>	\$ 50.00 ✓
1	Front footrest bracket <span style="float: right;">Seat ✓</span>	\$ 120.00 ✓
1	Brake pedal <span style="float: right;">RX</span>	\$ 60.00 X
1	Top cover <span style="float: right;">cut ✓</span>	\$ 120.00 ✓
1	Front side cover - R/H <span style="float: right;">cut ✓</span>	\$ 175.00 ✓
1	Front inner center cover (key side) <span style="float: right;">RX</span>	\$ 120.00 X
1	Rear footrest - R/H <span style="float: right;">svex</span>	\$ 28.00 X
1	Rear handle <span style="float: right;">RX</span>	\$ 180.00 X
1	Engine cover <span style="float: right;">cut 110 X</span>	\$ 480.00 X
1	Engine cover gasket <span style="float: right;">17 X</span>	\$ 75.00 X
1	Exhaust cover <span style="float: right;">cut ✓</span>	\$ 120.00 ✓
1	Master pump <span style="float: right;">Damage ✓</span>	\$ 480.00 ✓
		\$ 4,045.00
		Less 10%
		\$ 404.50
		\$ 3,640.50

Not Authorised  
 3/3/21  
 L/S \$ 2000  
 Zhe p/ls After rep  
 Hdys

1642  
 10%  
 1677.80

# EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : Mohammad Nur Khairul Bin  
Ahmad

Accident Date : 19-Feb-21

Vehicle No : FBE5706P

Vehicle Model : Yamaha X-1R

## Estimated Repair Costs

### Special Net Items

1	Number plate - (1 set) <i>for cur 10</i>	\$	28.00	<i>10</i>
2	Fork oils <i>max</i>	\$	30.00	<i>x</i>
2	Fork oil seals <i>max</i>	\$	56.00	<i>x</i>
1	Steering cone (1 set) <i>max ✓</i>	\$	75.00	<i>60</i>
1	Engine oil <i>max</i>	\$	35.00	<i>x</i>
1	E.R.P. IU <i>max</i>	\$	180.00	<i>x</i>
1	Rear box <i>max</i>	\$	150.00	<i>—</i>
1	Rear box bracket <i>one</i>	\$	380.00	<i>180</i>
		\$	<u>934.00</u>	

### S/No. Labour

1	To provide towing service	\$	30.00	<i>25</i>
2	To remove, refit and align front fork tubes	\$	<i>11</i> 180.00	<i>x</i>
3	To check electrical and headlamp focusing	\$	<i>11</i> 80.00	<i>x</i>
4	To provide paint work	\$	580.00	<i>400</i>
5	To provide labour	\$	420.00	<i>250</i>
		\$	<u>1,290.00</u>	

**Grand Total**

**\$ 5,864.50**

Singapore Dollars: Five Thousand Eight Hundred Sixty-Four and Cents: Fifty only

**EROFIA MOTOR TRADING PTE LTD**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*2552.8*