

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21002868/GVF3E2

Date: 14/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 999993943
Claimant Vehicle No : SML9430R Insured Vehicle No : SMV2734H
Date of Loss: 28/02/2021 Nature of Claim: TP Claim No: 2700864645SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SML9430R
Make & Model: TOYOTA PRIUS PLUS, 1.8 (A) Engine No: 2ZR0D50751
Reg. Date: 12/06/2019 (Man. Year: 2019) Chassis No: JTDZS3EU90J040666
Colour: Black Odometer: 140267 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Arivo 6 mm Rear Left Side: Firenza 6 mm
Front Right Side: Arivo 6 mm Rear Right Side: Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 03/03/2021
Date Inspected: 03/03/2021 Inspected At: LUMENS AUTO PTE LTD (HQ)
9 Sin Ming Industrial Estate Sector C #01-38
S(575644)
Singapore 575644
Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT RH DOOR	Repair	0.00 F	*- F
2	1		*REAR RH DOOR	Repair	0.00 F	*- F
3	1		*REAR RH FENDER	Repair	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >