



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. BICYCLE

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	SET XT GEAR	DENTED	1,000.00	1,000.00
1	XT PEDAL	CUT	100.00	100.00
1	SET SHIMANO M800 BRAKE	BENT	240.00	240.00
1	GARY FISHER SUPERFLY 100 }		9,750.00	9,750.00
1	FRT RIM }	BENT	-	-
1	HANDLEBAR }	CRACKED	-	-
1	FRT FORK ASSY }	BENT	-	-
1	BODY FRAME CARBON FIBRE }	CRACKED	-	-
	LESS 10% DISCOUNT		-	-1,109.00
			11,090.00	9,981.00
	<b>LABOUR</b>			
	WORKMANSHIP.		200.00	200.00
	INSTALLATION.		20.00	20.00
			220.00	220.00
	<b>GRAND TOTAL</b>		<b>11,310.00</b>	<b>10,201.00</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>10,201.00</b>

Report Ref No. CS3/CTI18000820/T1td3e2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.