



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref:	CS3/LPC21001237/T1vd3e2-1
300 BEACH ROAD			Date:	11/03/2021
#17-04/07 THE CONCOURSESINGAPORE 199555			Code:	LPC2
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GX 1336R	Veh. Inspected	SLA 7939Z	
Policy No.	Z/20/VC00/106147	Coverage (\$)	0.00	
Claim No.	20/21/21/VC00/024161	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	03/03/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MR053REH104546939	Colour	SILVER	
Odometer	55655 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	YOKOHAMA	6 mm	
L/H Front Tyre	205/55 R16	YOKOHAMA	6 mm	
R/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm	
L/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/01/2021	Inspection Date	26/01/2021	
Survey held at	BLK 3012 #01-2026 BEDOK INDUSTRIAL PARK E			
Repairer	POWER AUTO CAR SERVICES			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	