

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21002896/BBA3Q2  
**Date:** 10/06/2021**REFERENCE**

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  |              |
| <b>Claimant Vehicle No :</b> | SLA8858S                             | <b>Insured Vehicle No :</b> | SJR1156P     |
| Date of Loss:                | 27/02/2021                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 1884119721SG |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SLA8858S</b>                   |             |                   |
| Make & Model:               | AUDI A8 L, 3.0 TFSI QU (A)        | Engine No:  | CGW018025         |
| Reg. Date:                  | 30/04/2012 (Man. Year: 2011)      | Chassis No: | WAUZZZ4H8CN004674 |
| Colour:                     | Blue                              | Odometer:   | 107986 km         |
| Engine Capacity:            | 2995 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

**CONDITION OF TYRES**

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 225/45 R19   | Rear Tyre Size:  | 225/45 R19   |
| Front Left Side:  | Pirelli 5 mm | Rear Left Side:  | Pirelli 5 mm |
| Front Right Side: | Pirelli 5 mm | Rear Right Side: | Pirelli 5 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 25,458.45         | 5,098.57          | 20,359.88         | 79.97         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 5,200.00          | 1,610.00          | 3,590.00          | 69.04         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>30,658.45</b>  | <b>6,708.57</b>   | <b>23,949.88</b>  | <b>78.12</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>5,350.00</b>   |                   |               |

|                                                             |                  |                 |                  |              |
|-------------------------------------------------------------|------------------|-----------------|------------------|--------------|
| (S\$)                                                       | 30,658.45        | 5,350.00        | 25,308.45        | 82.55        |
| <b>+ GST 7.00/7.00% (S\$)</b>                               | 2,146.09         | 374.50          | 1,771.59         | 82.55        |
| <b>Nett Amount (S\$)</b>                                    | <b>32,804.54</b> | <b>5,724.50</b> | <b>27,080.04</b> | <b>82.55</b> |
| <b>+ Car Rental (7.0 x S\$180.00/day + 7.00% GST) (S\$)</b> |                  | 1,348.20        |                  |              |
| <b>+ Doc/Search Fee (S\$)</b>                               |                  | 7.45            |                  |              |
| <b>Nett Liability (S\$)</b>                                 |                  | <b>7,080.15</b> |                  |              |
| <b>Global Sum Settlement (S\$)</b>                          |                  | <b>6,800.00</b> |                  |              |

INSPECTION

Date of Assignment: 03/03/2021

Date Inspected: 03/03/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Team Autopro Pte Ltd (sin Ming) (HQ)  
 160 SIN MING DRIVE, #01-14 SIN MING AUTOCITY  
 Singapore 575722

**Adjuster:** Lim Teow Guan**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                         | Condition     | Repairer's  | Amount       |
|-----|-----|----------|-------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *BOOTLID                            | Repair        | 3,650.30 FL | *- FL        |
| 2   | 1   |          | *BOOTLID LOGO                       | Necessary     | 121.70 FL   | *107.70 FL   |
| 3   | 1   |          | *BOOTLID EMBLEM A 8 L               | Necessary     | 130.20 FL   | *130.20 FL   |
| 4   | 1   |          | *BOOTLID EMBLEM 3.0T                | Necessary     | 121.00 FL   | *83.60 FL    |
| 5   | 1   |          | *BOOTLID EMBLEM QUOTTRO             | Necessary     | 101.00 FL   | *85.00 FL    |
| 6   | 2   |          | *BOOTLID LAMP                       | Not Damaged   | 2,402.00 FL | *- FL        |
| 7   | 2   |          | *BOOTLID NUMBER PLATE LAMP          | Not Damaged   | 223.40 FL   | *- FL        |
| 8   | 1   |          | *BOOTLID CAMERA UNIT                | Not Damaged   | 900.97 FL   | *- FL        |
| 9   | 1   |          | *BOOTLID INNER LOCK                 | Not Damaged   | 430.75 FL   | *- FL        |
| 10  | 1   |          | *BOOTLID OUTER LOCK                 | Not Damaged   | 288.96 FL   | *- FL        |
| 11  | 1   |          | *BOOTLID LOCK SWITCH                | Not Damaged   | 289.70 FL   | *- FL        |
| 12  | 1   |          | *BOOTLID LOCK STRIKER               | Not Damaged   | 200.33 FL   | *- FL        |
| 13  | 1   |          | *BOOTLID WEATHERSTRIP               | Not Damaged   | 400.93 FL   | *- FL        |
| 14  | 1   |          | *BOOTLID INNER TRIM BOARD           | Not Damaged   | 788.75 FL   | *- FL        |
| 15  | 2   |          | *BOOTLID HINGE                      | Not Damaged   | 381.94 FL   | *- FL        |
| 16  | 2   |          | *BOOTLID HINGE GARNISH              | Not Damaged   | 160.40 FL   | *- FL        |
| 17  | 1   |          | *BOOTLID LIFTER MOTOR               | Not Damaged   | 490.97 FL   | *- FL        |
| 18  | 1   |          | *REAR BUMPER                        | Broken        | 2,400.70 FL | *2,236.45 FL |
| 19  | 2   |          | *REAR BUMPER SIDE RETAINER          | Necessary     | 181.94 FL   | *110.00 FL   |
| 20  | 2   |          | *REAR BUMPER SIDE BRACKET           | Not Necessary | 179.58 FL   | *- FL        |
| 21  | 1   |          | *REAR BUMPER CENTRE BRACKET         | Not Necessary | 200.71 FL   | *- FL        |
| 22  | 1   |          | *REAR BUMPER REINFORCEMENT          | Bent          | 688.96 FL   | *688.96 FL   |
| 23  | 2   |          | *REAR BUMPER REINFORCEMENT BRACKET  | Not Necessary | 377.40 FL   | *- FL        |
| 24  | 1   |          | *REAR BUMPER DIFFUSER               | Not Damaged   | 488.79 FL   | *- FL        |
| 25  | 1   |          | *REAR BUMPER DIFFUSER OUTER GARNISH | Cut           | 833.70 FL   | *833.70 FL   |
| 26  | 1   |          | *REAR BUMPER TOW CAP                | Not Damaged   | 117.30 FL   | *- FL        |
| 27  | 1   |          | *REAR BUMPER WIRING HARNESS         | Not Damaged   | 600.71 FL   | *- FL        |
| 28  | 4   |          | *REAR BUMPER REVERSE SENSOR         | Scratched     | 889.20 FL   | *889.20 FL   |
| 29  | 1   |          | *REAR END PANEL                     | Not Damaged   | 1,489.70 FL | *- FL        |
| 30  | 1   |          | *REAR END PANEL TOP GARNISH         | Not Damaged   | 140.20 FL   | *- FL        |
| 31  | 2   |          | *TAIL LAMP                          | Not Damaged   | 2,601.40 FL | *- FL        |
| 32  | 1   |          | *TAIL LAMP BASE PANEL               | Not Damaged   | 388.90 FL   | *- FL        |
| 33  | 2   |          | *TAIL LAMP LOWER BRACKET            | Not Damaged   | 202.60 FL   | *- FL        |
| 34  | 1   |          | *TAIL LAMP OUTER GARNISH            | Not Damaged   | 70.20 FL    | *- FL        |
| 35  | 2   |          | *REAR FENDER INNER TRIM             | Not Damaged   | 1,601.80 FL | *- FL        |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                       | Condition     | Repairer's | Amount     |
|-----|-----|----------|-----------------------------------|---------------|------------|------------|
| 36  | 1   |          | *SPARE TYRE TOP BOARD             | Not Damaged   | 711.80 FL  | *- FL      |
| 37  | 1   |          | *SUNDRIES                         | Not Necessary | 80.00 FS   | *- FS      |
| 38  | 1   |          | *BOOTLID SEALANT                  | Not Necessary | 100.00 FS  | *- FS      |
| 39  | 1   |          | *BOOTLID LAMP CLIPS               | Not Necessary | 60.00 FS   | *- FS      |
| 40  | 1   |          | *BOOTLID LAMP SEAL                | Not Necessary | 60.00 FS   | *- FS      |
| 41  | 1   |          | *BOOTLID INNER TRIM BOARD CLIPS   | Not Necessary | 60.00 FS   | *- FS      |
| 42  | 1   |          | *REAR BUMPER CLIPS                | Not Necessary | 60.00 FS   | *- FS      |
| 43  | 1   |          | *REAR BUMPER DIFFUSER CLIPS       | Not Necessary | 60.00 FS   | *- FS      |
| 44  | 4   |          | *REAR BUMPER REVERSE SENSOR SEAL  | Necessary     | 192.00 FS  | *192.00 FS |
| 45  | 1   |          | *REAR NUMBER PLATE W/GARNISH      | Not Damaged   | 120.00 FS  | *- FS      |
| 46  | 1   |          | *REAR END PANEL SEALANT           | Not Necessary | 100.00 FS  | *- FS      |
| 47  | 1   |          | *REAR END PANEL TOP GARNISH CLIPS | Not Necessary | 60.00 FS   | *- FS      |
| 48  | 2   |          | *TAIL LAMP CLIPS                  | Not Necessary | 120.00 FS  | *- FS      |
| 49  | 2   |          | *TAIL LAMP SEAL                   | Not Necessary | 120.00 FS  | *- FS      |
| 50  | 1   |          | *TAIL LAMP BASE PANEL SEALANT     | Not Necessary | 100.00 FS  | *- FS      |
| 51  | 1   |          | *TAIL LAMP OUTER GARNISH CLIPS    | Not Necessary | 60.00 FS   | *- FS      |
| 52  | 2   |          | *REAR FENDER INNER TRIM CLIPS     | Not Necessary | 120.00 FS  | *- FS      |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                          |                  |                 |
|----------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$\$)</b>                                  | <b>26,720.89</b> | <b>5,356.81</b> |
| <b>- List Item Discount on L Items 5.00/5.00% (\$\$)</b> | 1,262.44         | 258.24          |
| <b>Total Parts (\$\$)</b>                                | <b>25,458.45</b> | <b>5,098.57</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                    | Lab.Type | Repairer's      | Amount          |
|--------------------------------|--------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>     |                                |          |                 |                 |
| 1                              | R&R BOOTLID COMPONENT          | New      | 200.00          | 0.00            |
| 2                              | R&R BOOTLID CAMERA UNIT        | New      | 200.00          | 0.00            |
| 3                              | R&R BOOTLID LIFTER MOTOR       | New      | 200.00          | 0.00            |
| 4                              | R&R REAR BUMPER REVERSE SENSOR | New      | 100.00          | 60.00           |
| 5                              | UPHOLSTERY                     | New      | 300.00          | 0.00            |
| 6                              | CHECK WIRING                   | New      | 100.00          | 30.00           |
| 7                              | DIGNOSTIC RESET FAULT CODE     | New      | 300.00          | 120.00          |
| 8                              | PANEL BEATING                  | New      | 1,800.00        | 800.00          |
| 9                              | RUST PROOFING                  | New      | 200.00          | 0.00            |
| 10                             | SPRAY PAINTING                 | New      | 1,800.00        | 600.00          |
| <b>Gross Labour Cost (S\$)</b> |                                |          | <b>5,200.00</b> | <b>1,610.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >