Interview (\$

Tech. Invs (\$

West end (\$

Reper Former:

Lump Sum / LB J: CF

Photos

Others

TOTAL



# SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report <u>correctly</u> the details of the accident to speed up the claims process.

2. This Form must be <u>completed by the Policyholder and/or the Authorised Driver</u>

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

S. Any false reporting may be referred to the Police for Investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### **ACCIDENT STATEMENT**

Date of Submission Date of Accident Exact Location of Accident Additional Location Information Country/State of Loss

02/03/2021 01:10 (SGT) 27/02/2021 15:30 (SGT) Balestier Rd, Singapore BALESTIER RD BEFORE JALAN DUSUN, AH HOOD RD Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number

**SLA8858S** 

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner Company Reg No. Email Address Mobile Phone No Alternative Phone No.

Yes HONG SEH MOTOR PTE LTD 1XXXXX320D kenlow@hongseh.com.sg (Phone) +65-97777073 (Office) +65-97777073

VEHICLE PARTICULARS

Manufacturer

Model Variant

Exact purpose for which vehicle was being used at time of accident

Vehicle Category

Are you claiming under your own insurance policy for repair to your vehicle?

Audi A8

Private use

No - Claiming third party Private car

INSURANCE COMPANY

Name of Insurance Company Type of Coverage Fleet Policy

Policy Number Cover Note Number

Comprehensive Yes

P2423040

DRIVER

Name of Driver NRIC No Date Of Birth Occupation

LEE SUN GMIN SXXXX920H 26/10/1975 Indoor



Date Of Driving Pass 12/01/2015 Driving experience 6 YEARS AND 1 MONTH Gender Male Mobile Number (Phone) +65-97832991 Alt. Phone Number **Email Address** kenlow@hongseh.com.sg Address 38 Trevose Crescent Address complement # 04-25 Postcode 297722 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Hirer Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Insurance Company of Other Vehicle Owned by Driver

Type of Accident Collision - Head to Rear Weather Conditions Clear Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?

No
Number of vehicles involved in the accident

Was anybody injured in the Accident?

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged?

Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s)

soliciting/offering accident claims assistance?

No

DETAILS OF POLICE ACTION

Was the accident reported to the police?

Was notice of intended Prosecution given?

No If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

My vehicle was already stopped due to heavy traffic flows ahead. While waiting, suddenly I felt an impact from behind and saw a car had already hit onto my vehicle rear bumper.

ATTACHMENT(S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

No
Was there any audio recorded?

No

### DETAILS OF OTHER VEHICLE PROPERTY 1

Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies
  of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims [including the malling of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents/including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

VERIFY BY AJAX MARS (ARC) REPORTING OFFICER AIZAM BIN ATAN

Policyholder's Signature Date & Time: Oriver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name: NRIC/IIN No.

| SKETCH PLAN                              |                                       |        |  |
|--|---------------------------------------|--------|--|
|  | 191919                                | )      |  |
|  | 750                                   | P      | Balestre   |
|  |                                       |        | R2   |
| DESCRIBE CIRCUMSTA                       | ANCES OF THE ACCIDENT                 |        | <b>共共和国的</b>   |
| REFER TO ATTACHED                        | STATEMENT. A: S                       | LA 88  | 585  |
|  | B: S:                                 | JR 115 | 6 P  |
|  |                                       |        |  |
|  |                                       |        | ,  |
|  |                                       |        |  |
|  | 1                                     |        |  |
|  |                                       |        |  |
|  |                                       |        |  |
|  |                                       |        |  |
|  |                                       | 1      |  |
|  |                                       |        |  |
|  |                                       |        |  |
|  |                                       |        |  |
|  |                                       |        |  |
| DECLARATION                              |                                       | 5 140  |  |
|  | irticulars are true in every respect. | 7      | VERIFY BY AIAX MARS (ARC) REPORTING OFFICER AIZAM BIN ATAN |
| Policyholder's Signature<br>Date & Time: | ( debut or out the bolloyholder)      |        | Reporting Centre Personnel's Signature Name:               |

#### **ACCIDENT STATEMENT (2000 characters)**

My vehicle was already stopped due to heavy traffic flows ahead. While waiting, suddenly I felt an impact from behind and saw a car had already hit onto my vehicle rear bumper.

Taxi Voucher No.:

#### DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -AIZAM BIN ATAN

MARS Officer

Registered Owner or Driver's Signature

Job Complete Date/Time

1 March 2021 at 1:00 PM

Date/Time:

1 March 2021 at 1:00 PM

intended C. Jf. Rebase Datails

## Team AutoPro Pte Ltd 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722

| SJE:              |              | Vehicle Nos : | SLA 8858 S |
|-------------------|--------------|---------------|------------|
| Date of Survey :  |              | Model :       | AUDI A8 L  |
| Date of ReSurvey: | After-Paint: | Year:         |            |
| Contacts :        |              | Chassis No:   |            |

## \* AGREED Cost Of Repair and Repair Day/s with SJE \*

Amount:

Working Day:

| Nos. | PARTS                             | Qty  |      | Unit S\$         | TOTAL S\$           |        |
|------|-----------------------------------|------|------|------------------|---------------------|--------|
| 1    | BOOTLID                           | 1    | \$   | 3,650.30         | \$ 3,650.30         | WIT R  |
| 2    | BOOTLID LOGO                      | 1    | \$   | 121.70           | \$ 107.70 121.70    |        |
| 3    | BOOTLID EMBLEM 'A 8L'             | 1    | \$   | 130.20           | \$ 130.20           | THEC / |
| 4    | BOOTLID emblem '3.0T'             | 1    | \$   | 121.00           | 5 83-60 121:00      | INCO   |
| 5    | BOOTLID EMBLEM 'QUOTTRO'          | 1    | \$   | 101.00           | \$ 85-00 101.00     |        |
| 6    | BOOTLID LAMP                      | 2    | \$   | 1,201.00         | \$ 2,402.00         |        |
| 7    | BOOTLID NUMBER PLATE LAMP         | 2    | \$   | 111.70           | \$ 223.40           |        |
| 8    | BOOTLID CAMERA UNIT               | 1    | \$   | 900.97           | \$ 900.97           |        |
| 9    | BOOTLID INNER LOCK                | 1    | \$   | 430.75           | \$ 430.75           | -      |
| 10   | BOOTLID OUTER LOCK                | 1    | \$   | 288.96           | \$ 288.96           | 100.   |
| 11   | BOOLID LOCK SWITCH                | 1    | \$   | 289.70           | \$ 289.70           | > NDX  |
| 12   | BOOTLID LOCK STRIKER              | 1    | \$   | 200.33           | \$ -200.33          |        |
| 13   | BOOTLID WEATHER STRIP             | 1    | \$   | 400.93           | \$ 400.93           |        |
| 14   | BOOTLID INNER TRIM BOARD          | 1    | \$   | 788.75           | \$ 788.75           |        |
| 15   | BOOTLID HINGE                     | 2    | \$   | 190.97           | \$ 381.94           |        |
| 16   | BOOTLID HINGE GARNISH             | 2    | \$   | 80.20            | \$ 160.40           |        |
| 17   | BOOTLID LIFTER MOTOR              | 1    | \$   | 490.97           | \$ 490.97           | )      |
| 18   | REAR BUMPER                       | 1    | \$   | 2,400.70         | \$ 2236-45 2,400.70 | BRV    |
| 19   | REAR BUMPER SIDE RETAINER         | 2    | \$ . | 55 - 60 90.97    | \$ 110.00 181.94    | NELV   |
| 20   | REAR BUMPER SIDE BRACKET          | 2    | \$   | 89.79            |                     | XMM    |
| 21   | REAR BUMPER CENTRE BRACKET        | 1    | \$   | 200.71           | \$ 200.71           | XNN    |
| 22   | REAR BUMPER REINFORCEMENT         | 1    | \$   | 688.96           | \$ \sqrt{688.96}    | BTV    |
| 23   | REAR BUMPER REINFORCEMENT BRACKET | 2    | \$   | 188.70           | \$ 277.40           | KUN    |
| 24   | REAR BUMPER DIFFUSER              | 1    | \$   | 488.79           | \$ -488.79          | NDX    |
| 25   | REAR BUMPER DIFFUSER OUTER CHROME | 1    | \$   | 833.70           | \$ 833.70 \833.70   | cuts   |
| 26   | REAR BUMPER TOW CAP               | 1    | \$   | 117.30           | \$ 117.30           | NDX    |
| 27   | REAR BUMPER WIRING HARNESS        | 1    | \$   | 600.71           | \$ 600.71           | NDX    |
| 28   | REAR BUMPER REVERSE SENSOR        | 4    | \$   | 222.30           | \$ \sqrt{889.20}    | scV    |
| 29   | REAR END PANEL                    | 1    | \$   | 1,489.70         | \$ 1,489.70.        | NDX    |
| 30   | REAR END PANEL TOP GARNISH        | 1    | \$   | 140.20           | \$ 140,20           | )      |
| 31   | TAIL LAMP                         | 2    | \$   | 1,300.70         | \$ 2,601.40         |        |
| 32   | TAIL LAMP BASE PANEL              | 1    | \$   | 388.90           | \$ -388.90          |        |
| 33   | TAIL LAMP LOWER BRACKET           | 2    | \$   | 101,30           | \$ 202.60           | LNDX   |
| 34   | TAIL LAMP OUTER GANISH            | 1    | \$   | 70.20            | \$ 70.20            | 1      |
| 35   | REAR FENDER INNER TRIM            | 2    | \$   | 800.90           | \$ -1,601.80        |        |
| 36   | SPARE TYRE TOP BOARD              | 1    | \$   | 711.80           | \$ 711.80           | )      |
|      |                                   |      | F    | arts Sub Total : | \$ 25,248.89        |        |
|      |                                   | DISC |      | 5%               | \$ 1,262.44         |        |

PARTS TOTAL: \$ 23,986.45

5164.81

@5% <u>258.24</u> 4906.57

| Nos. | SPECIAL NETT                     | Qty | Unit \$\$         | TOTAL S\$  |
|------|----------------------------------|-----|-------------------|--|
| 1    | SUNDRIES                         | 1   | \$ 80.0           |  |
| 2    | BOOTLID SEALANT                  | 1   | \$ 100.0          |  |
| 3    | BOOTLID LAMP CLIPS               | 1   | \$ 60.0           | 0 \$ 60.00   |
| 4    | BOOTLID LAMP SEAL                | 1   | \$ 60.0           | 0 \$ 60.00   |
| 5    | BOOTLID INNER TRIM BOARD CLIPS   | 1   | \$ 60.0           | 0 \$ 60.00   |
| 6    | REAR BUMPER CLIPS                | 1   | \$ 60.0           | 0 \$ 60.00   |
| 7    | REAR BUMPER DIFFUSER CLIPS       | 1   | \$ 60.0           | \$ 60.09   |
| 8    | REAR BUMPER REVERSE SENSORS SEAL | 4   | \$ 48.0           | 0 \$ 192.00  |
| 9    | REAR NUMBER PLATE W/ COWLING     | 1   | \$ 120.0          | 0 \$ 120.00  |
| 10   | REAR END PANEL SEALANT           | 1   | \$ 100.0          | 0 \$ 100.00  |
| 11   | REAR END PANEL TOP GARNISH CLIPS | 1   | \$ 60.00          | 0 \$ 66.00   |
| 12   | TAIL LAMP CLIPS                  | 2   | \$ 60.0           | 0 \$ 120.00  |
| 13   | TAIL LAMP SEAL                   | 2   | \$ 60.0           | 0 \$ 120.00  |
| 14   | TAIL LAMP BASE PANEL SEALANT     | 1   | \$ 100.0          | 0 \$ 100.00  |
| 15   | TAIL LAMP OUTER GANISH CLIPS     | 1   | \$ 60.0           | 0 \$ 60.00   |
| 16   | REAR FENDER INNER TRIM CLIPS     | 2   | \$ 60.0           |  |
|      |                                  | SI  | PECIAL NETT TOTAL | \$ /22.00 1,472.00   |
|      |                                  |     |                   |  |
| Nos. | LABOUR                           |     |                   | \$\$   |
| 2    | R&R BOOTLID COMPONENT            |     |                   | \$ 200,00  |
| 3    | R&R BOOTLID CAMERA UNIT          |     |                   | \$ 200.00  |
| 4    | R&R BOOTLID LIFTER MOTOR         |     |                   | \$ 200.00  |
| 5    | R&R REAR BUMPER REVERSE SENSOR   |     |                   | \$ 60:00 100.00  |
| 6    | UPHOLSTERTY                      |     |                   | \$ 900:00  |
| 7    | DIGNOSTIC RESET EATH T CODE      |     |                   | \$ 30,00 400.00  |
| 8    | PANEL BEATING                    |     |                   | \$ 500.00 1800.00  |
| 9    | RUST PROOFING                    |     |                   | \$ 800.00 1,800.00   |
| 10   | SPRAY PAINTING                   |     |                   | \$ 600.00 1,800.00   |
| 0.   |                                  |     | LABOUR TOTAL      | THE RESERVE OF THE PARTY OF THE |
|      | rvoy Resurvey                    |     |                   |  |
|      | 12021 4/3/2021                   |     | PARTS TOTAL       | : \$ 23,986.45   |
| 23   | ehrs 13eolig<br>ian 7 grine      | SP  | ECIAL NETT TOTAL  |  |
| 7-1  |                                  |     | LABOUR TOTAL      |  |
| 40   | ea Torin                         |     | GRAND TOTAL       |  |
| Me   | Www                              |     | CACALL TOTAL      | 30,038.43  |
| 0    | (VVIII)                          |     |                   |  |
|      |                                  |     |                   |  |
|      |                                  |     | 0,0               | 4906.57  |
|      |                                  |     | TAR15             | 4700 37  |
|      | Lump sum repair                  |     | PARTS             |  |
|      | Lump sum repair                  |     | SN                | 192.00   |
|      | Lump sum repair<br>Repair days 6 |     |                   | 192.00   |
|      | Lump sum repair<br>Repair days 6 |     | SN                | 192.00   |
|      | Lump sum repair<br>Repair days 6 |     | SN                | 192.00<br>1610.00<br>6708.57   |
|      | Lump sum repair<br>Repair days 6 |     | S N<br>LABOZIR    | 192.00   |
|      | Lump sum repair<br>Repair days 6 |     | SN                | 192.00   |

4/5 5,35 0/2 Tatin lin

## MOTORCAR (Rear)

| NAC     | INC    | Item  | Took | 110 | 10       |
|---------|--------|---|------|-----|----------|
|         |        | Rear Number Plate                                     | CON  | AC  | V        |
| 1 1.3,8 | 993627 | Rear Number Plate Base                                | -    | _   | _        |
| 1139    | 993630 | Rear Number Plate Garnish                             | -    | -   | -        |
| 1140    | 993632 | Reaf Number Plate Lamn                                | +    | -   | -        |
| 1141    | 992958 | Rear Bumper   | BR   | -   | -        |
| 1142    | 993085 | Rear Bumper Upper                                     | DR   | 1   | -        |
| 1143    | 993017 | Rear Bumper Lower                                     | +    | -   | $\vdash$ |
| 1144    | 993054 | Rear Bumper Side                                      | 4    | -   | -        |
| 1145    | 993103 | Rear Bumper Tow Cover                                 | -    | -   | -        |
| 1146    | 992341 | Rear Bumper Clips                                     | -    | -   | -        |
| 1147    | 992976 | Rear Bumper Bracket                                   | -    | -   | _        |
| 1148    | 993068 | Rear Bumper Side Retainer                             | -    | -   | _        |
| 1149    | 993045 | Rear Bumper Reinforcement                             | NEL  | V   | 2        |
| 1150    | 992910 | Kear Bumper Repm                                      | BI   | V   |          |
| 1151    | 993077 | Rear Bumper Sponge                                    | -    | -   | _        |
| 1152    | 792999 | Rear Burner Dames                                     | -    | -   | _        |
| 1153    | 993040 | Rear Bumper Protector                                 | -    | -   | -        |
| 1154    | 333030 | Kear Bumper Pad                                       | -    | -   | -        |
| 1155    | 993026 | Rear Bumper Moulding                                  | 1    | -   | -        |
| 1156    | 993044 | Rear Bumper Reflector                                 | -    | -   | -        |
| 1157    | 993023 | Rear Bumper Lower Spoiler                             | -    | -   | -        |
| 1158    | 994023 | Reverse Sensor  | 51   | V   | -        |
| 1160    | 993327 | Rear End Panel  |      |     |          |
| 1161    | 993339 | Rear End Panel Top Garnish                            |      |     |          |
| 1162    | 990333 | Rear End Panel Inner Trim Boot Compartment Inner Trim |      |     |          |
| 1163    | 993851 | Rear LH Taillamp                                      | -    |     |          |
| 1164    | 993853 | Rear I.H Taillama Camlah                              | -    | _   |          |
| 1165    | 993859 | Rear LH Taillamp Panel                                | -    | _   | _        |
| 1166    | 333110 | Rear RH Taillamn                                      | -    | -   | _        |
| 1167    | 993853 | Rear RH Taillama Camich                               | -    |     | _        |
| 1168    | 333823 | Rear RH Taillaron Panel                               | -    | -   | -        |
| 1169    | 993554 | Rear Apron Panel                                      | -    | -   | -        |
| 1170    | 992895 | Bootlid   |      |     | _        |
| 1171    | 991328 | Bootlid Emblem  | NEC  | V   | 4        |
| 1172    | 990356 | Bootlid Handle  |      |     |          |
|         | 993230 | Bootlid Moulding                                      |      |     |          |
| 1175    | 005222 | Bootlid Reflector Bootlid Lamp LH                     |      |     |          |
| 1176    | 992899 | Bootlid Lamp RH                                       |      |     |          |
| 1177    | 995243 | Bootlid Lock  | -    |     |          |
| 1178    | 990377 | Bootlid Rubber  | -    |     | _        |
| 1179    | 990382 | Bootlid Hinge   | -    | -   | _        |
| 1180    | 993877 | Bootlid Spoiler                                       | 1    | -   | -        |
| 1181    | 994543 | Tailgate  | 1    | -   | _        |
| 1182    | 991328 | Tailgate Emblem                                       |      | -   | -        |
| 1183    | 994643 | Tailgate Outer Handle                                 |      |     | -        |
| 1184    | 994640 | Tailgate Moulding                                     |      |     |          |
| 1185    | 994343 | Tailgate Gamish                                       |      |     |          |
| 1187    | 994048 | Tailgate Reflector                                    |      |     |          |
| 1188    | 994646 | Tailgate Lamp Tailgate Protector                      |      |     |          |
| 1189    | 994676 | Tailgate Wiper Arm                                    |      |     |          |
| 1190    | 994677 | Tailgate Wiper Blade                                  |      |     |          |
| 191     | 994679 | Tailgate Wiper Nozzle                                 |      |     |          |
| 192     | 994555 | Tailgate Wiper Motor                                  | -    | _   |          |
| 193     | 994602 | Tailgate Glass.                                       |      | _   |          |
| 194     | 994606 | Tailgate Glass Rubber                                 |      |     |          |
| 195     | 004604 | Tailgate Glass Rubber                                 |      |     |          |
| 195     | 004607 | Tailgate Glass Moulding                               |      |     |          |
| 196     | 994007 | Tailgate Glass Sealant                                |      |     |          |
| 197     | 994629 | Tailgate Lock   |      |     |          |
| 198     | 00461  | Tailgate Rubber .                                     |      |     |          |
| 199     | 994611 | Failgate Hinge  |      |     |          |
| 200     | 994594 | Tailgate Damper                                       |      | 1   |          |

|    |      |              | Vehicle Not - SLA  | 188          | 5      | 85     |
|----|------|--------------|--|--------------|--------|--------|
|    | NAC  | INC          | Item   | CON          |        |        |
|    | 1202 |              | Spare Tyre Board   |              |        | 1      |
|    | 1203 | 994328       | Spare Tyre Panel   |              |        | 1      |
| -  | 1204 |              | Spare Tyre   |              |        |        |
| 1  | 1205 | 994326       | Spare Tyre Lock Screw  |              |        |        |
| 1  | 1206 | 993787       | Spare Tyre Cover   |              |        |        |
| ŀ  | 1207 | 995323       | Triangle Breakdown Sign  |              |        |        |
| J  | 1208 |              | CD Changer Assy  |              |        |        |
| 1  | 1209 |              | Antenna  |              |        |        |
| 1  | 1210 |              | Centre Exhaust Pipe Assy .   |              |        |        |
| 1  | 1211 |              | Centre Exhaust Mounting  |              |        |        |
| 1  | 1212 |              | Rear Exhaust Pipe  |              |        | Γ      |
| 1  | 1213 | 993357       | Rear Exhaust Chrome Pipe   |              |        |        |
| 1  | 1214 | 993361       | Rear Exhaust Mounting  |              |        |        |
| ŀ  | 1215 | 993358       | Rear Exhaust Heat Shield   |              |        |        |
| ŀ  | 1217 | 995223       | Rear LH Chassis Member<br>Rear RH Chassis Member   | -            |        | _      |
| ŀ  | 1218 | 993165       | Rear LH Fender   | -            |        | -      |
| ŀ  | 1219 |              | Rear LH Fender Protector   | -            | _      | -      |
| ŀ  |      | 993470       | Rear LH Fender Inner Panel   | -            | _      | -      |
| ł  | 1221 |              | Rear LH Fender Inner Trim  | -            | -      | -      |
| 1  | 1222 |              | Rear LH Fender Inner Garnish   | -            |        | -      |
| Ì  | 1223 | 993425       | Rear LH Pender Inner Shield  | -            | -      | -      |
|    | 1224 | 993621       | Rear LH Mudflap  |              |        | -      |
| Į. | 1225 |              | Rear LH Wheel Rim  |              |        | -      |
| 1  | 1226 |              | Rear LH Rim Cover  |              |        |        |
| ŀ  | 1227 | 995065       | Rear LH Tyre<br>Rear RH Fender   |              |        |        |
| ŀ  | 1220 | 993450       | Rear RH Fender Protector   |              |        |        |
| h  | 1230 | 993420       | Rear RH Fender Inner Panel   |              |        |        |
| ŀ  | 1231 | 993431       | Rear RH Fender Inner Trim  |              | -      | _      |
| t  | 1232 | 993415       | Rear RH Fender Inner Garnish   | -            | -      |        |
|    | 1233 | 993425       | Rear RH Fender Inner Shield  | -            | -      |        |
|    | 1234 | 993622       | Rear RH Mudflap  |              |        | _      |
|    | 1235 | 993934       | Rear RH Wheel Rim  |              | $\neg$ | _      |
| 1  | 1236 | 994025       | Rear RH Rim Cover  |              |        | _      |
| 1  | 1237 | 995065       | Rear RH Tyre   |              |        |        |
| 1  | 1238 | 995162       | Rear Fender Extension Panel LH   |              |        |        |
| H  | 1239 | 9934/11      | Rear Fender Extension Panel RH   |              |        |        |
| H  | 1240 | 993430       | Rear Fender Inner Top Gamish   |              |        | -4     |
| H  | 1242 | 993673       | Rear Fender 1/4 Glass .  Rear Fender 1/4 Glass Rubber  | _            | 1      |        |
| 1  | 1243 | 993453       | Rear Fender 1/4 Glass Rubber Rear Fender 1/4 Glass Sealant   | -            | -      | _      |
| T  | 1244 | 993949       | Rear Windscreen Glass  |              | -      | - 1    |
| 1  | 1245 |              | Rear Windscreen Rubber   |              | -      |        |
| L  | 1246 | 993961       | Rear Windscreen Moulding   |              |        | 100    |
| 1  | 1247 | 993955       | Rear Windscreen Sealant  |              |        | 130    |
| 1  | 1248 | 994729       | Third Brake Light  |              |        | 30     |
|    | 1249 | 993385       | Rear Fender Air Grille   |              |        | 1      |
|    |      |              | Fuel Lid   |              |        | 湯      |
|    |      |              | Fuel Neck<br>Fuel Tank   |              |        | 1      |
|    | 1253 | 992184       | Fuel Tank Bracket  | _            | 1      | Cep    |
|    |      |              | Fuel Tank Float  | -            | 7      | - 50   |
|    |      | 990247       | Sticker  | -            | -      | 300    |
| 1  |      |              | unifor diffuser chrome   | MI           | 7      | 200    |
| T  |      |              | The state of the s | 44           | 4      | 200    |
| Γ  |      |              |  | -            | 1      | PACE A |
| 1  |      |              |  | -            | -      | SALE S |
| 1  |      |              |  | -            | -      | SIGN   |
| 1  |      |              |  | -            | -      | COL    |
| 1  | -    |              |  | -            | -      | ATOM S |
| 1  |      |              |  | -            | -      | 100    |
| r  |      |              |  | -            | 1      | 300    |
|    |      |              |  |              | i      | 1      |
|    |      |              |  |              | 4      | 50     |
|    | 100  | 200 CH - 100 |  | CO. C. C. C. | 1000   | 1000   |

No of Items:

Assessor: Teliku
3/3/2021

## > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars                                 |                          |      |
|---|--------------------------|------|
| Owner ID Type:  |                          |      |
| Owner ID:   | Company                  |      |
| Vehicle Details   | 320D                     |      |
| Vehicle No.:  | SLA8858S                 |      |
| Vehicle to be Exported:                                   | No.                      |      |
| Intended Deregistration Date:                             |                          |      |
| Vehicle Make:   | 15 Mar 2021              |      |
| Vehicle Model:  | AUDI                     |      |
| Primary Colour:   | A8L 3.0 TFSI QU (SR+HID) |      |
| Manufacturing Year:                                       | Blue                     |      |
| Engine No.:   | 2011                     |      |
| Chassis No.:  | CGW018025                |      |
| Maximum Power Output:                                     | WAUZZZ4H8CN004674        |      |
| Open Market Value:  | 213.0 kW (285 bhp)       |      |
| Original Registration Date:                               | \$83,668.00              |      |
| First Registration Date:                                  | 30 Apr 2012              |      |
| Transfer Count:   | 30 Apr 2012              |      |
| Actual ARF Paid:  |                          |      |
| Intended PARF Rebate Details                              | \$83,668.00              |      |
| PARF Eligibility:   |                          |      |
| PARF Eligibility Expiry Date:                             | Yes                      |      |
| PARF Rebate Amount:                                       | 29 Apr 2022              | TE E |
| Intended COE Rebate Details                               | \$46,017.00              |      |
| COE Expiry Date:  | 20.4 2000                |      |
| COE Category:   | 29 Apr 2022              |      |
| COE Period(Years):  | E - Open Category        |      |
| QP Paid:  | 10                       |      |
| COE Rebate Amount:  | \$84,590.00              |      |
| Total Rebate Amount:                                      | \$9,393.00               |      |
| information contained herein is correct as at 15 Mar 2021 | \$55,410.00              |      |

The information contained herein is correct as at 15 Mar 2021