

輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

26/02/2021

Owner: J&A TRADING & TRANSPORT SERVICES LLP

ESTIMATE TO REPAIR TOYOTA HIACE - PC8125R

1pc	rear LH taillamp	300.80	h	\$	371.70	✓
1pc	rear LH taillamp lower garnish		h	\$	371.45	x
1pc	rear LH taillamp lower garnish retainer		h	\$	174.80	✓
1pc	rear bumper		h	\$	371.10	✓
1pc	rear LH fender		h	\$	1,712.85	✓
				\$	3,001.90	
	less 25%			\$	750.48	
	balance c/f			\$	2,251.43	
	tuffkote		na	\$	100.00	x
	wiring			\$	60.00	201
	spray painting			\$	1,000.00	3001
	labour charges			\$	1,000.00	3001
	Total			\$	4,411.43	

Not withstanding
11 Day 8 900k
Penny After Paim 2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

